

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	🔍 Find Next
---	---	----------	---	---	---	---	--------	---	---------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: CS3/CTI21010677/T1vf3		
3 ANSON ROAD #16-00		Date: 18/10/2021		
SPRINGLEAF TOWERS SINGAPORE 079909		Code: CTI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SJW 7540Y	Veh. Inspected	SLB 4950D	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM21D205892/C02	Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	18/10/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/10/2021	Inspection Date	18/10/2021	
Survey held at	Blk 5 #01-582 Defu Lane 10			
Repairer	HENG MOTOR SERVICES			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				