

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

18-Oct-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1679 U

1 pc	Bonnet	\$	2,253.80/BT
1 pc	Bonnet insulator	\$	230.10XSVC
1 pc	Bonnet lock	\$	127.30XSVC
2 pcs	Bonnet hinge o/s & n/s @\$118.70	\$	237.40XSVC
1 pc	Bonnet weatherstrip	\$	61.30XSVC
1 pc	Front bumper	\$	430.90/Cut
1 pc	Front bumper centre grille cover - Upper	\$	108.50XSVC
1 pc	Front bumper emblem "HYUNDAI"	\$	28.00XSVC
1 pc	Front bumper o/s side upper bracket	\$	12.00/nec
2 pcs	Front bumper o/s & n/s side retainer @ \$39.30	\$	78.60/nec
1 pc	Front bumper o/s fog lamp @ \$642.50	\$	642.50XSVC
1 pc	Front bumper o/s fog lamp moulding @ \$93.00	\$	186.00/Scr 93
1 pc	Front o/s headlamp	\$	1,198.80/Cra
1 pc	Front o/s fender	\$	490.70/Def
1 pc	Front o/s fender inner shield	\$	114.70/DIS
1 pc	Front n/s & o/s fender garnish- Delta @\$15.30	\$	15.30XSVC
1 pc	Front n/s fender emblem "Blue-drive"	\$	26.20/nec
1 pc	Front n/s & o/s absorber mounting@\$105.00	\$	105.00? XSVC
1 pc	Front n/s & o/s wheelhub assy@\$153.00	\$	153.00? XSVC
1 pc	Front n/s & o/s absorber bearing @\$34.00	\$	34.00? XSVC
1 pc	Front n/s & o/s lower arm@\$439.00	\$	439.00? XSVC
1 pc	Front n/s & o/s absorber@\$330.00	\$	330.00? XSVC
1 pc	Front n/s & o/s tie rod end@\$61.00	\$	61.00? XSVC
1 pc	Front n/s & o/s knuckle arm@\$547.00	\$	547.00? XSVC
1 pc	Front n/s & o/s knuckle arm bearing @\$109.00	\$	109.00? XSVC
1 pc	Front n/s & o/s rim@\$246.00	\$	246.00? XSVC
1 pc	Front n/s & o/s stablizer link@\$86.00	\$	86.00? XSVC
1 pc	Front o/s wheel cover	\$	116.00/Scr
		\$	8,468.10
Less 20%		\$	1,693.62
		\$	6,774.48

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

11-Sep-20

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1679 U

1 pc

Washer tank

	\$	57.50	✓ DT
Less 35%	\$	20.13	
- 20%	\$	37.38	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

*THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.*

S/NETT

1 pc	Front bumper clips	\$	48.00	free
1 set	Front o/s fender inner shield clips	\$	28.00	free
	Sundry	\$	50.00	X succ
	To check wiring on headlamp	\$	50.00	30
	To adjust & focus front head lamps	\$	80.00	30
	To check for front o/s wheel alignment	\$	80.00	60
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same.	\$	800.00	540
	To putty and spray painting on front bumper, front o/s fender, bonnet, front door RH	\$	900.00	800 80
	To apply rustproofing on the repaired and replaced panels.	\$	80.00	30
	door sticker RH	\$	8,890.48	
		\$	50	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Thuan@Lkhauto.com
82235769

18/10/21 1330

P/p bfr paint photo

4 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

F: ~~5528246~~

5523.76