

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121010681/VUF3N2**Date:** 13/06/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHC1041P **Insured Vehicle No :** GBK5838K

Date of Loss: 15/10/2021 Nature of Claim: TP Claim No: CDMCG21001999

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC1041P**

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEJU080636

Reg. Date: 03/09/2018 (Man. Year: 2018) Chassis No: KMHC851CVKU107386

Colour: Blue Odometer: 459103 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,043.77	1,043.77	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	330.00	330.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,373.77	1,373.77	0.00	0.00
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	1,373.77	1,100.00	273.77	19.93
+ GST 7.00/7.00% (S\$)	96.16	77.00	19.16	19.93
Nett Amount (S\$)	1,469.93	1,177.00	292.93	19.93

INSPECTION

Date of Assignment: 18/10/2021

Date Inspected: 18/10/2021 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 1.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 02 Nov 2021)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1041P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR MIRROR ASSY LH	Cracked	1,391.70 FL	*1,391.70 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,391.70	1,391.70
- List Item Discount on L Items 25.00/25.00% (S\$)					347.93	347.93
Total Parts (S\$)					1,043.77	1,043.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	150.00	150.00
2	SPRAY PAINTING CHARGE	New	150.00	150.00
3	WIRING CHARGE	New	30.00	30.00
Gross Labour Cost (\$)			330.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >