

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	🔍 Find   Next
---	---	----------	---	---	---	---	--------	---	---------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref: CS3/EQI21010683/R1vf3		
5 MAXWELL ROAD		Date: 18/10/2021		
#17-00 TOWER BLOCK				
MND COMPLEXSINGAPORE 069110		Code: EQI		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	YF 7667C	Veh. Inspected	SJQ 4590D	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM21HO01546/MT	Excess (\$)	0.00	
Assign From	MELODY TEOH	Assign Date	18/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/10/2021	Inspection Date	19/10/2021	
Survey held at	SAN TEE AUTO PTE LTD BLK 1019 #01-388 YISHUN INDUSTRIAL PARK A SINGAPORE 768761			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				