

REPAIR PERFORMA INVOICE

CHINA TAIPING

|                |                   |
|----------------|-------------------|
| Vehicle number | SLH5112T          |
| Make / Model   | TOYOTA WISH       |
| Chassis number | JTDGG20W10J005356 |
| Accident date  | 14/10/21          |
| Reference      | 2110-11           |

Qty Particulars Unit Price - SGD \$

| PARTS REPLACEMENT - LIST ITEMS         |                                    |                              |
|----------------------------------------|------------------------------------|------------------------------|
| 1                                      | REAR BUMPER                        | 543.9 765.50 / Def / Cut     |
| 2                                      | REAR BUMPER RETAINER               | 151.20 ?                     |
| 2                                      | REAR BUMPER BRACKET                | 120.30 / nec                 |
| 2                                      | REAR BUMPER REFLECTOR              | 136 173.60 / XNN / cra       |
| 2                                      | REAR BUMPER DAMPER                 | 192.30 ? XNN                 |
| 1                                      | KEYLESS SENSOR                     | 144.2 281.60 ? / Def         |
| 1                                      | KEYLESS SENSOR HOLDER              | 102.20 ? XNN                 |
| 1                                      | TAILGATE                           | 1275 1370.62 / DT            |
| 1                                      | TAILGATE WEATHERSTRIP              | 229.10 XNN ? X SVC           |
| 1                                      | TAILGATE LOCK                      | 361 509.20 X SVC / jam       |
| 1                                      | TAILGATE LOCK STRIKER              | 53.17 X SVC                  |
| 2                                      | TAILGATE EMBLEM - VALVE MATIC      | 54.59 / nec                  |
| 1                                      | TAILGATE EMBLEM - LOGO             | 65.29 / nec                  |
| 1                                      | TAILGATE GLASS MOULDING            | 180.00 / nec                 |
| 1                                      | TAILGATE OUTER CHROME GARNISH      | 239 386.50 / nec CRA X SVC ✓ |
| 2                                      | TAILGATE LAMP                      | 854.56 X SVC ? X SVC         |
| 1                                      | TAILGATE INNER TRIM BOARD          | 299.7 331.90 X SVC ? / Cut   |
| 2                                      | TAILLAMP                           | 643 1054.76 ? / X SVC        |
| 2                                      | TAILLAMP BRACKET                   | 360.60 ? XNN                 |
| 1                                      | END PANEL                          | 420 803.87 ? / DT            |
| 1                                      | END PANEL TOP GARNISH              | 218.9 382.61 ? / Cut         |
| 1                                      | SPARE TYRE TOP BOARD               | 500.23 ? Xr                  |
| 1                                      | SPARE TYRE COMPARTMENT             | 1203.60 ? X SVC / jam XNC Δ  |
| 1                                      | WIPER MOTOR                        | 481.3 687.12 X SVC           |
| 1                                      | WIPER BLADE                        | 46.47 X SVC                  |
|                                        |                                    | 10860.89                     |
| Less 25%                               |                                    | 2715.23                      |
|                                        |                                    | 8145.66                      |
| PARTS REPLACEMENT - SPECIAL NETT ITEMS |                                    |                              |
| 1 SET                                  | REAR BUMPER CLIP nec               | 40.00 20                     |
| 2 SET                                  | REAR FENDER INNER TRIM CLIP nec    | 120.00 30                    |
| 1 SET                                  | TAILGATE INNER TRIM BOARD CLIP nec | 60.00 20                     |
| 1 SET                                  | REAR BUMPER TOP RUBBER             | 200.00 ? / nec 100           |
| 1 SET                                  | REAR NUMBER PLATE nec              | 80.00 / 50                   |
| 1 SET                                  | WINDSCREEN SEALANT nec             | 120.00 60                    |
| 1 SET                                  | REVERSE SENSOR                     | 400.00 / 200 Cut             |
| Subtotal                               |                                    | 1020.00                      |
| Balance C/F                            |                                    | 9165.66                      |

**REPAIR PERFORMA INVOICE**

CHINA TAIPING

|                |                   |
|----------------|-------------------|
| Vehicle number | SLH5112T          |
| Make / Model   | TOYOTA WISH       |
| Chassis number | JTDGG20W10J005356 |
| Accident date  | 14/10/21          |
| Reference      | 2110-11           |

| Qty | Particulars                                          | Unit Price - SGD \$ |
|-----|------------------------------------------------------|---------------------|
|     | <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>        |                     |
| 1   | REVERSE CAMERA <span style="color: blue;">cut</span> | 500.00 X NC         |
|     | Balance C/F                                          | 500.00              |

| <u>LABOUR AND MISCELLANEOUS CHARGES</u> |                                                        |                            |
|-----------------------------------------|--------------------------------------------------------|----------------------------|
| 1                                       | CHECK WIRING AND LIGHTNING SYSTEM                      | 60.00 30                   |
| 2                                       | REMOVE TRIMS & GARNISHES <del>FOR HOTWORK REPAIR</del> | 200.00 1. 30               |
| 3                                       | REMOVE AND REFIT EXHAUST SILENCER                      | 150.00 XNW                 |
| 4                                       | REMOVE, REFIT REAR WINDSCREEN                          | 200.00 170                 |
| 5                                       | REMOVE, REFIT AND REPLACE REVERSE SENSOR               | 200.00 30                  |
| 6                                       | PANEL BEATING ON AFFECTED AREAS                        | 1800.00 <del>800</del> 600 |
| 7                                       | SPRAY PAINTING ON AFFECTED AREAS                       | 1800.00 <del>400</del> 800 |
| 8                                       | APPLY ANTI RUST ON AFFECTED AREAS                      | 150.00 30                  |
| Subtotal                                |                                                        | 4560.00                    |
| Grand total                             |                                                        | 13725.66                   |

Thewar@lkkauto.com

82235769

19/10/21 1300

L/S after repair photo

X 1 days w/p

S

~~F: \$4500~~

F: 4500

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: