

ASS. REC. BY: TGUM

REF:

CS/CT121010688/Bnf3Denise

## ASSIGNMENT

From:

Date: 19/10/2021Veh No: GBJ 2354PYr Regn: 20/2/2019

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: GBJ 2354PMake: Joyota Regius Acec.c. 2754at Workshop m/s Bifrost AutoColour: White

A/C: Insured / Std / NI / NA

of 8 Kaki Bt Ave # Premier #01-49Sp. Reading: 75397

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No: LGD 8362663

Policy No.:

C/No: GDH2011016999

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: NI / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 195/15R: 195/15

Remark: The veh had commenced its

repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: 68,000/-

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal. 6 mmR/Bal. 6 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal. 6 mmL/Bal. 6 mm

Est. Repairs:

7 days

Res.: Yes or No

D.O.A. 16/10/2021D.O.I. 19/10/2021

Lum Sum:

%

3 Val.: Yes or No

Survey held at Bifrost AutoDes. of Damages: FR / Rear / O/S / NI / U/C / Rooftop orCA / REV / REP. / 24 HRS SWP

Vehicle: IN / OUT

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 12,000/- - 13,000/-
25/8	Recommended COR is LS \$12,950.00 Lump Sum \$12950 and 7 days (Red. \$17164.62, 579%) TGUM Min
	MV 68,000/-
	PV 17,720/-
	NV 50,280/- TGUM Min 1/11/2021

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: 71) 25/8/22☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐: Site Insp (\$ 1)☐

: Interview (\$ )

☐

: Tech. Invs (\$ )

☐

: Weekend (\$ )

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L.C. / 12950

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	18/10/2021 17:59 (SGT)
Date of Accident	16/10/2021 14:27 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TAMPINES AVE 8 - ST 71 JUNCTION AVE 5
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ2354P
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	Yes
Name of Registered Owner	KJX DELIVERY SERVICES
Company Reg No	53431731J
Email Address	KISAME9797@HOTMAIL.COM
Mobile Phone No	(Phone) +65-90099619
Alternative Phone No	(Home) +65-90099619

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Regius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2754

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5121708473
Cover Note Number	-

### DRIVER

Name of Driver	TAN JUN XIONG
NRIC No	S9744497H

Date Of Birth	08/12/1997
Occupation	Outdoor
Date Of Driving Pass	30/05/2018
Driving experience	3 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90099619
Alt. Phone Number	-
Email Address	KIETHTKL1997@HOTMAIL.COM
Address	205 TPY NORTH #07-1171
Address complement	-
Postcode	310205
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHED

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM4898M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car




On the above date and time, I was travelling along Tampines Ave 8 in the direction of Tampines St 11. On approaching the junction of Tampines Ave 5, the traffic light is in my favour. Suddenly a maroon color car bearing plate number SJM 489BM suddenly dash out in front of me and collided with my vehicle. My vehicle was badly damage.

Declaration

We declare the foregoing particulars are true in every respect.

   
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

SHUYI  
Witnessed by Reporting Centre Personnel

VEHICLE NO. <b>GBJ 2354 P</b>	MAKE & MODEL <b>Toyota Hiace</b>	<u>AUTO / PRIVATE</u>
DATE OF ACCIDENT	<b>16 / OCT / 2021</b>	LOC.
TIME OF ACCIDENT	<b>02:27</b> AM / PM	
LOCATION OF ACCIDENT	<b>Tampines Ave 8 - Street 71 Junction Ave 5</b>	
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / <u>PRIVATE USE</u> / PRIVATE HIRE	
NAME OF OWNER	<b>KJX Delivery Services</b>	
EMAIL: <b>KISAME9747@HOTMAIL.COM</b>	Office:	MOBILE: <b>90099619</b>
NRIC		
CLAIM TYPE	OD / <u>THIRD PARTY</u> / REPORTING ONLY	
FLEET POLICY:	YES / <u>NO</u> ?	
INSURANCE CO.	<b>NTUC</b>	
TYPE OF COVERAGE	<u>Comprehensive</u> / Third Party / Third Party Fire & Theft	
POLICY NO	<b>5121708473</b>	
NAME OF DRIVER	AS ABOVE / IF NO. <b>Tan Jun Xiong</b>	
NRIC	<b>S9744497 H</b>	
DATE OF BIRTH	<b>08 / 12 / 1997</b>	
ANY PASSENGER	YES / NO :	
NAME OF PASSENGER	<b>/</b>	
GENDER OF PASSENGER	MALE / FEMALE <b>X</b>	
OCCUPATION	<u>Outdoor</u> / Indoor	
DATE OF DRIVING PASS	<b>30 / 05 / 2018</b>	
GENDER	<u>Male</u> / Female	
CONTACT NO.	Mobile: <b>90099619</b> Office: Home:	
EMAIL	<b>KIETHKLI997@HOTMAIL.COM</b>	
ADDRESS	<b>205 TOA PAYOH NORTH #07-1171 S(310205)</b>	
DOES DRIVER OWN OTHER VEHICLE?	NO / If yes, Reg No. <b>CL1174</b>	
RELATIONSHIP	<u>Employee</u> / If No:	
WEATHER CONDITION	<u>Clear</u> / Raining / Other:	
ROAD SURFACE	<u>Dry</u> / Wet / Other:	
ANY INJURIES	No / If yes, Who? <b>1) DRIVER</b>	
CONTACT NO.		
POLICE REPORT	No / If yes, Where?	
NOTICE OF INTENDED PROSECUTION GIVEN?	NO/IF YES, WHO?	
VEHICLE B NO.	<b>SJM 4898M</b> Any Passenger: <b>/</b>	
NAME		
CONTACT NO.		
VEHICLE C NO	Any Passenger:	
VEHICLE D NO	Any Passenger:	
VEHICLE E NO	Any Passenger:	
VEHICLE F NO	Any Passenger:	
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	YES / <u>NO</u>	
WAS THERE ANY AUDIO RECORDED?	YES / <u>NO</u>	
SCENE ACCIDENT PHOTOS TAKEN?	YES / <u>NO</u>	

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	731J
<b>Vehicle Details</b>	
Vehicle No.:	GBJ2354P
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	REGIUS ACE 2.8 DX DIESEL TURBO AT 2WD
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1GD8362663
Chassis No.:	GDH2011016999
Maximum Power Output:	-
Open Market Value:	\$36,947.00
Original Registration Date:	20 Feb 2019
First Registration Date:	20 Feb 2019
Transfer Count:	2
Actual ARF Paid:	\$1,848.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	19 Feb 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,263.00
COE Rebate Amount:	\$17,720.00
<b>Total Rebate Amount:</b>	<b>\$17,720.00</b>

The information contained herein is correct as at 01 Nov 2021

OK

MV 68,000/r

PV 17,720/r

NY 50,280/r

TGC in line  
1/11/2021

## BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No: GBJ2354P  
 Model and make: Toyota Reguis  
 Chassis: GDH2011016999

Qty Spare partsList price

1	Bonnet	\$	825.50	953.36	DDV
1	Bonnet emblem	\$	68.10	76.48	NECV
1	Bonnet RH hinge	\$		79.24	BTV
1	Bonnet LH hinge	\$		79.24	NDX
1	Bonnet lock	\$		145.50	JM
1	Bonnet lock catch	\$		97.30	NNX
1	Bonnet lock cable	\$		99.84	NECV
1	Bonnet stand	\$		42.03	NDX
1	Bonnet stand holder	\$		6.50	NDX
1	Wiper garnish	\$	596.70	558.79	BRV
1	Wiper garnish LH side cover	\$		48.18	BRV
1	Wiper garnish rubber	\$		35.78	NECV
1	Wiper tank	\$	52.20	105.93	BRV
2	Wiper tank motors	\$		450.58	NDX
1	Front bumper	\$	654.00	1,031.44	BRV
1	Front bumper lower grille	\$	264.20	458.39	BRV
1	Front bumper RH side grille	\$		139.84	NDX
1	Front bumper LH side grille	\$		139.74	BRV
1	Front bumper RH towing cover	\$		84.92	NDX
1	Front bumper LH towing cover	\$	40.00	84.92	BRV
1	Front bumper top beam	\$		218.04	BTV
1	Front bumper reinforcement	\$		459.66	DDV
1	Front bumper RH side retainer	\$	148.70	175.90	NECV
1	Front bumper LH side retainer	\$	148.70	175.90	NECV
1	Front bumper guide	\$		339.93	?NSX
1	Front grille	\$	568.90	1,072.50	BRV
1	RH headlamp (HID)	\$		2,539.80	BRV
1	LH headlamp (HID)	\$		2,539.80	BRV
1	Radiator assy	\$		1,990.00	?NDX
1	Radiator spare tank	\$	399.20	592.29	BRV
1	Radiator fan motor	\$		1,281.90	NDX
1	Radiator fan cowling	\$		317.30	BRV
1	Radiator top hose	\$		105.84	NDX
1	Radiator lower hose	\$		106.24	NDX
1	Aircon condenser	\$		1,431.90	DDV
1	Aircon fan motor	\$		1,281.90	NDX
1	Aircon aluiminim pipe	\$		508.90	?NDX
1	Aircon discharge pipe	\$		272.44	?NDX
1	Aircon suction pipe	\$		556.30	?NDX
1	Aircon condenser RH side garnish	\$		128.50	?NDX
1	Aircon condenser LH side garnish	\$		128.50	?NDX
1	Intercooler	\$	1558.19	1,614.00	DDV
1	Intercooler cover	\$		215.98	?NDX
1	Intercooler bracket	\$		145.72	?NDX

1	Support panel	\$	✓ 554.19	DDV
1	Support panel top cover	\$	-198.40	NDX
1	Front brace panel	\$	✓ 117.40	BTU
1	Air resonator box	\$	✓ 309.07	DDV
1	Air cleaner box	\$	758.99	NDX
1	Air hose	\$	✓ 211.94	DDV
1	Horns	\$	87.60 219.48	DDV
1	Front wire harness	\$	1,250.88	NDX
1	Front inner panel	\$	821.40 1,013.58	DDV
1	Front LH corner panel	\$	✓ 233.90	MIS
1	Front LH side mirror	\$	✓ 266.80	BRU
1	Front LH side mirror bracket	\$	✓ 178.40	MIS
1	Front LH side mirror cover	\$	✓ 71.34	DDV
1	Front LH door outer pillar	\$	✓ 881.70	DDV
1	Front LH door	\$	✓ 1,571.80	DDV
1	Front LH door side mirror	\$	-973.40	NDX
1	Front LH door upper hinge	\$	98.10 174.34	BTU
1	Front LH door lower hinge	\$	98.10 174.34	BTU
1	Front LH door checker	\$	147.09	NDX
1	Front LH door weatherstrip	\$	-219.54	NDX
1	Front LH door step garnish	\$	-179.29	NDX
1	Front LH door lock	\$	716.38	NDX
1	Dashboard			

\$18881.61 33,339.49  
 -25% \$ 4720.40 8,334.87  
 \$ 14161.21 25,004.62

#### Qty Spare parts

		Special Nett	
1set	Front bumper clips	\$	70.00-NNX
1	Radiator coolant	\$	30.00 60.00 NEC
1	Front LH door LTA sticker	\$	30.00 50.00 NEC
1set	Front LH door inner trim board	\$	60.00 NDX
1	Front LH door sticker	\$	50.00 NNX
1set	Front grille clips	\$	30.00 70.00 NEC
1	Front number plate	\$	25.00 60.00 CUT
1	Front windscreen glass sealant	\$	70.00 } NNX
1	Front windscreen glass inner seal	\$	50.00 }
			115.00

#### Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$	800.00 1,600.00
Spray painting on affected panels	\$	800.00 1,400.00
Check wiring and lighting system	\$	-120.00 NNX
Apply rust coating chemical on affected panels	\$	100.00 NNX
Remove and reinstall front windscreen glass to assist repair	\$	200.00-NNX

Remove, replace and reinstall dashboard and all attachments items to assist repair	\$	450.00	NNX
Remove and replace aircon condenser, pipes and motor to assist repair. To refill gas	\$	120.00	240.00 ✓
Remove and replace radiator assy, hoses and fan assy to assist repair. To refill coolant	\$	80.00	240.00 ✓
Remove and reinstall front LH door inner components to new door	\$	80.00	120.00 ✓
Remove and replace intercooler and pipes to assist repair	\$	50.00	100.00 ✓

Survey  
19/10/2021  
Terim Win  
1600hrs

Resurvey  
20/10/2021  
Terim Win  
1455hrs

Final amount \$ 1930.00 30,114.62

Lump sum repair  
Repair days 7

Parts	14,161.21
SN	115.00
Labour	1,930.00
	<hr/> 16,206.21
@20%	3,241.24
	<hr/> 12,964.97

LS 12,950/2

Terim Win  
1/11/2021

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: