

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (S) PTE LTD		Ref: CC3/MSG21010689/Uqf3n2		
4 SHENTON WAY #21-01		Date: 05/11/2021		
SGX CENTRE 2 SINGAPORE 068807		Code: MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBN 5976D	Veh. Inspected	PC 3697P	
Policy No.	MSD/VMS/21-516469-WTT	Coverage (\$)	0.00	
Claim No.	MSC/V/21-000459	Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIN B MADI)	Assign Date	18/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KDH2230022697	Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/10/2021	Inspection Date	18/10/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				