

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21010693/URS3Q2
Date: 07/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100496645
Claimant Vehicle No :	SJB7787M	Insured Vehicle No :	SKW26A
Date of Loss:	13/10/2021	Nature of Claim:	TP
		Claim No:	2156619342SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB7787M		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR (A)	Engine No:	4A910072838
Reg. Date:	24/01/2008 (Man. Year: 2007)	Chassis No:	JMYSRCY2A8U004144
Colour:	Black	Odometer:	625689 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,008.00	4,643.60	4,364.40	48.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,630.00	910.00	35.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,548.00	6,273.60	5,274.40	45.67
Approved Total (Overridden) (S\$)		5,000.00		

(S\$)	11,548.00	5,000.00	6,548.00	56.70
+ GST 7.00/7.00% (S\$)	808.36	350.00	458.36	56.70
Nett Amount (S\$)	12,356.36	5,350.00	7,006.36	56.70
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,592.00		

INSPECTION

Date of Assignment: 18/10/2021

Date Inspected: 18/10/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER SPORT EVO	Distorted	2,500.00 F	*1,350.00 FL
2	1		*REAR BUMPER LOWER SPORT	Distorted	1,800.00 F	*1,500.00 FL
3	1		*REAR BUMPER TOW COVER	Deformed	38.00 F	*38.00 FL
4	1		*SET REAR BUMPER REFLECTOR LED	Cracked	250.00 F	*220.00 FL
5	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	120.00 F	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	318.00 F	*308.00 FL
7	1		*REAR BUMPER TOP BEAM	Serviceable	122.00 F	*- FL
8	1		*REAR END PANEL	Dented	545.00 F	*525.00 FL
9	1		*REAR END PANEL TOP GARNISH	Not Necessary	168.00 F	*- FL
10	1		*TAILLAMP O/S	Cracked	485.00 F	*381.00 FL
11	1		*REAR FENDER INNER TRIM O/S	Torn	282.00 F	*282.00 FL
12	1		*REAR EXHAUST ASSY	Repair	1,650.00 F	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
14	1		*SET REAR BUMPER RALLIART DECAL	Necessary	350.00 FS	*200.00 FS
15	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
16	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,008.00	5,104.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	460.40
Total Parts (\$\$)	9,008.00	4,643.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	0.00
5	TO SPRAY RUST PROOFING	New	60.00	30.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	850.00
Gross Labour Cost (S\$)			2,540.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >