

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SMQ 2320U

Adjustment of Spare Parts Costs for Repairs			Estimate
Item	Qty	Vehicle parts description	by
1	1	front bumper — CRU	1080.00 ✓
2	1	front bumper side retainer RH ? — BR	150.00 90 ✓
3	1	front bumper fog lamp RH X nn	295.00
4	1	front bumper fog lamp cover RH X nn	165.00
5	1	front bumper reinforcement X nn	750.00
6	1	front bumper sponge X nn	155.00
8	1	front headlamp RH — CNT	2250.00 2130-35 ✓
9	1	front headlamp bracket holder RH X nn	155.00
10	1	front fender RH — DD	680.00 ✓
11	1	front fender inner shield RH ? — CRU	298.00 ✓
12	1 set	front fender inner shield fasteners RH ? — CRU	58.00 20 ✓
13	1	front RH absorber X nn	625.00
14	1	front RH wheel bearing X nn	510.00
15	1	front RH knuckle arm X nn	690.00
16	1	front RH lower arm X nn	565.00
17	1	front RH wheel hub X nn	753.90
18	1	front support panel X nn	980.00
21	1	front grille X nn	550.00
22	1	front engine lower garnish X nn	250.00
			10959.90
Less 10%			1095.99
			9863.91
Special nett item			
1	1	front RH rim — CNT	320.00 300 ✓
2	1 set	front bumper sensor RH X nn	350.00
3	1	front LH tyre X nn	300.00
Total parts			
			970.00

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and expandable items.	600.00	400
Carry out body cavity preservation	100.00	30
To remove and replaced damaged parts including straightening and repositioning replacement parts & panel	600.00	400

beat		
Check wiring and realign headlamp focus	80.00	30
to perform 4 wheel alignment	100.00	60
Remove & reinstall front bumper sensor	80.00	30
to clear and reset RH headlamp module fault code	300.00	100
remove and reinstall front RH undercarriage components	180.00	X
Total labour	2040.00	

Steve (LKK) WKL PL
 L/S
 My PL sy
 4 dys

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 4083-43
 M- 300
 L- 1050
 5433.43
 L/S- 4346-74
 = 4350