

ASSIGNMENT

From:

Date:

Estimated Cost:

OR / TP / WS / TP / RES / OD / RES / EVA / INV / MV

To inspect Vehicle Not

at Workshop m/b

Insured: SHC 5587E

Policy No.

Claims No. S1M033JJ

Sum Insured:


Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Ret. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

BIA / PR Sent

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Cum Sum:

%

3 Vol.: Yes or No

QA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 2320U

Yr Regn:

7/5/13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor

Truck / Trailer or

Make:

BMW 316

c.b. 1598

Colour:

Silver

A/O: Insured / Std / N / N

Sp. Reading

974.95

T/Radio: Insured / Std / N / N

Eng/No:

C/No:

WRA 30120401 722342

Gen. Cond: Good / Fair / Poor / Bad

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD AIR / m or

Tyre Size:

F1 225/SR17

R1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

20/2/21

D.O.A.

19/10/21

Survey held at

Win Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or

Frt RH

The U/C / CHASSIS frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-40K

25/10/21

LS \$4350 confirmed by email (Red 9071.91, 67%)

Date/Time, File, Pass to:



: Prel. Report



: Final Report

Date/Time, File Return to:

25/10/21-typist

Days Of Repair: 4

Resurvey No. of Trips: 2

Survey Fee:

Transportation:

S + RS, SI

Fines:

Others:

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wheel and (\$

Smart Claim

LS \$4350

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SMQ 2320U

Adjustment of Spare Parts Costs for Repairs			Estimate
Item	Qty	Vehicle parts description	by
1	1	front bumper / CR4 ?	1080.00
2	1	front bumper side retainer RH ?	150.00
3	1	front bumper fog lamp RH X	295.00
4	1	front bumper fog lamp cover RH X	165.00
5	1	front bumper reinforcement X	750.00
6	1	front bumper sponge X	155.00
8	1	front headlamp RH / CT	2250.00
9	1	front headlamp bracket holder RH X	155.00
10	1	front fender RH / DO	680.00
11	1	front fender inner shield RH ?	298.00
12	1set	front fender inner shield fasteners RH ?	58.00
13	1	front RH absorber X	625.00
14	1	front RH wheel bearing X	510.00
15	1	front RH knuckle arm X	690.00
16	1	front RH lower arm X	565.00
17	1	front RH wheel hub X	753.90
18	1	front support panel X	980.00
21	1	front grille X	550.00
22	1	front engine lower garnish X	250.00
			<hr/>
			10959.90
Less 10%			1095.99
			<hr/>
			9863.91

Special nett item			
1	1	front RH rim / CT	320.00
2	1set	front bumper sensor RH X	350.00
3	1	front LH tyre X	300.00
Total parts			<hr/>
			970.00

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and expandable items.	600.00	400
Carry out body cavity preservation	100.00	30
To remove and replaced damaged parts including straightening and repositioning replacement parts & panel	600.00	400

beat

Check wiring and realign headlamp focus	80.00	30
to perform 4 wheel alignment	100.00	60
Remove & reinstall front bumper sensor	80.00	30
to clear and reset RH headlamp module fault code	300.00	100
remove and reinstall front RH undercarriage components	180.00	X

Total labour

2040.00

Steve (LKK)

WHL PL

L/S

My PL sy

4 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: