

Our Job Ref No 305481105

Date 20/10/21

## FINALIZATION FORM


To LKK Fax \_\_\_\_\_  
Attn Mr THEVAN  
Vehicle Reg No SHC1150H CTPL 17/10/2021


The survey and estimates of the repairs of the above-mentioned vehicle are as follows -

1. The repair job shall bill to NTUC SML8430Y
2. The finalized amount shall be
- (a) Spare Parts after List discount \_\_\_\_\_
- (b) Labour Charges \_\_\_\_\_
- Total for Part-By-Part Repair Cost** \$0.00
- (c) Lumpsum Repair (if applicable)
- Total for Lumpsum repair cost after Less: \_\_\_\_\_
- Final Lumpsum Repair cost** \$3,150.00

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature:   
Name: MS. LOKE YY  
Tel: 62148355  
Fax: 65468156

Signature:   
Name: Thevan  
Date: 29/10/21

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC1150H ✓

Make : Toyota

Model : Prius

Date: 18.10.2021

Insurance: **AIG**MVA: **MS, LOKE YY**

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT FENDER HYBRID EMBLEM RH			\$86.50 <i>NEC</i>
1	FRONT FENDER SUB ASSY RH			\$945.30 <i>SR</i>
1	FRONT FENDER SHIELD RH			\$198.50 <i>SVC</i>
1	FRT FENDER RETAINER RH			\$86.30 <i>NEC</i>
1	FRONT BUMPER FOG LAMP			\$920.00 <i>SVC</i>
1	HEADLAMP RH			\$2,637.60 <i>SR</i>
1	FRONT BUMPER COVER			\$499.90 <i>Cut</i>
1	FRONT BUMPER SIDE BRACKET RH			\$82.30 <i>NEC</i>
10	FRONT BUMPER CLIPS			\$22.00 <i>NEC</i>
1	FRT WHEEL HUB CAP RH			\$177.70 <i>SR</i>
	<b>SUB TOTAL</b>			\$5,656.10
	<b>LESS 25%</b>			\$1,414.03
	<b>DISCOUNTED TOTAL</b>			<b>\$4,242.08</b>
	<b>FRT TYRE RH</b>	Nett		\$216.00 <i>SVC</i>
				<b>\$216.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$900.00 <i>700</i>
	SPRAY PAINTING CHARGE			\$600.00 <i>500</i>
	CHECK ALL LIGHTING			\$50.00 <i>300</i>
	TUFF KOTE			\$60.00 <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$1,610.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$6,068.08</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@lkhauto.com  
82235769

18/10/21 1630

U/S after repair photo  
3 days wp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: