

# A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113  
HP: 8386 8989 Email: atautoconsultant@gmail.com  
Co. Reg. No. : 53368526E

Date of Estimate: 18.10.2021  
Vehicle No: SFH6336D  
Owner: SIMPLICITY SLNS PTE LTD  
Date of Accident: 18.10.2021  
Make & Model: TOYOTA CHR  
Chassis No : ZYX10-2051365

Not withered  
11km @ 1250k  
Resurvey After Rain  
2 days

## ESTIMATE FOR ACCIDENT VEHICLE NOS SFH6336D

### PARTS

1	1 Rear bumper	855.10
2	1 Rear bumper low lid	397.60
3	1 Rear bumper reflector	
4	1 Rear wheel arch garnish RH	175.10
5	1 Tail lamp RH	
6	1 Tail lamp panel RH	
7	1 Rear fender RH (repair)	

SUB TOTAL  
LESS 25%  
DISCOUNTED SUB TOTAL

Bumper	\$1,239.00	✓
CL	\$450.00	✓
SL	\$180.00	X
CL	\$250.00	✓
SL	\$600.00	X
R	\$330.00	X
	\$0.00	
	<b>\$3,049.00</b>	
	<b>\$762.25</b>	
	<b>\$2,286.75</b>	

### S. NETT ITEM

1	1set Front bumper clips
2	1set Reverse sensor

SUB TOTAL  
LESS 0%  
DISCOUNTED SUB TOTAL

SL	\$50.00	✓
SL	\$320.00	X
	<b>\$370.00</b>	
	<b>\$0.00</b>	
	<b>\$370.00</b>	

### LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges / reverse sensor
5	Apply undercoating to above affected areas

SUB TOTAL (LABOUR)

	\$500.00	200l
	\$600.00	22cl
	\$120.00	5cl
SL	\$80.00	X
	<b>\$1,300.00</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: