

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHENG KIAT
43 CHUAN GARDEN

SINGAPORE 558560

ATTN:

Estimate No: MC1902224
Date: 19 Oct 2021
Policy No: MT/00642749/02
Veh Reg No: SKT3686R
Make/Model: HONDA CITY 1.5 SV
CVT

Your RefNo: SKT3686R
Claim Type: Third Party
Accident Date: 17/10/2021
TP Veh Reg No: YP8371X

Estimate Repair Cost to Vehicle No: SKT3686R

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	1 PC	502.90	✓
2 REAR BOOT HINGE LH & RH	2 PC	159.60	✓
3 REAR BOOT EMBLEM	1 PC	21.90	✓
4 REAR BOOT CITY LOGO	1 PC	21.50	✓
5 REAR BOOT IVTEC	1 PC	21.90	✓
6 REAR BOOT CHROME MOULDING	1 PC	98.50	✓
7 REAR BOOT NO PLATE LAMP LH & RH	2 PC	76.80	X
8 REAR BOOT REVERSE CAMERA	1 PC	625.90	✓
9 REAR BOOT OUTER SWITCH - CHECK PRICE	1 PC	0.00	✓
10 REAR BOOT INNER LOCK	1 PC	105.70	✓
11 REAR BOOT INNER LOCK STRIKER	1 PC	25.40	✓
12 REAR BOOT RUBBER	1 PC	84.20	50% ✓
13 REAR BOOT INNER TRIM	1 PC	99.70	✓
14 REAR BOOT INNER TRIM CLIPS	10 PC	55.00	✓
15 REAR BOOT STOPPER ROUND	2 PC	19.40	X
16 REAR BOOT STOPPER RECTANGLE - CHECK PRICE	2 PC	0.00	✓
17 REAR BOOT LAMP LH & RH	2 PC	194.40	✓
18 TAILAMP LH & RH	2 PC	450.80	✓
19 TAILAMP PANEL LH & RH	2 PC	196.40	✓
20 REAR BUMPER	1 PC	463.70	✓
21 REAR BUMPER SIDE RETAINER LH & RH	2 PC	27.80	✓
22 REAR BUMPER CLIPS	15 PC	82.50	✓
23 REAR END PANEL	1 PC	380.20	✓
24 REAR END PANEL TOP GARNISH	1 PC	66.60	✓
25 SPARE TYRE PANEL	1 PC	460.80	X
26 SPARE TYRE PANEL TOP TRIMBOARD	1 PC	89.20	✓
27 REAR WINDSCREEN MOULDING (COMPLETE)	1 PC	149.20	✓
28 REAR FENDER RH	1 PC	1,134.20	✓
29 REAR FENDER COWLING RH	1 PC	85.20	X
30 REAR FENDER COWLING CLIPS	8 PC	28.00	X
31 REAR FENDER AIR VENT RH	1 PC	35.70	✓
32 REAR FENDER INNER TRIM LH & RH	2 PC	136.60	✓
33 SPARE TYRE SCREW	1 PC	15.30	✓
34 REAR CHASSIS RH	1 PC	555.40	X
35 REAR EXHAUST PIPE	1 PC	320.40	X
36 REAR EXHAUST PIPE MOUNTING	3 PC	46.20	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Repairer's estimate must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ah Lim Motor Company

Not Authorized
11 By B
Meeting After Rain
10 days

cls Return

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHENG KIAT
43 CHUAN GARDEN

SINGAPORE 558560

ATTN:

Estimate No: MC1902224
Date: 19 Oct 2021
Policy No: MT/00642749/02
Veh Reg No: SKT3686R
Make/Model: HONDA CITY 1.5 SV
CVT

Your Ref No: SKT3686R
Claim Type: Third Party
Accident Date: 17/10/2021
TP Veh Reg No: YP8371X

Estimate Repair Cost to Vehicle No :SKT3686R

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		6,837.00	
	Less 20%	1,367.40	5,469.60
Special Nett			
37 REVERSE SENSOR	1 SET	400.00	200.00
38 NUMBER PLATE	1 PC	35.00	—
39 INNER SEAL	1 PC	20.00	—
40 WINDSCREEN SEALANT	1 PC	40.00	—
		495.00	495.00
LABOUR			
41 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
42 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
43 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
44 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	100.00
45 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	280.00	X
46 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50.00
47 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	90.00	✓
48 TO REALIGN, DISMANTLE AND REINSTALL/REPLACE EXHAUST PIPE.	1 PC	80.00	60.00
49 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL, SPARE TYRE PANEL, REAR FENDER RH, REAR CHASSIS RH, TAILAMP PANEL LH & RH. TO KNOCK & REPAIR REAR FENDER LH, REAR CHASSIS LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	1400.00
50 TO SPRAY REAR BOOT, REAR BUMPER, END PANEL, SPARE TYRE PANEL, REAR FENDER LH & RH, REAR CHASSIS LH & RH	1 PC	1,400.00	1200.00
		3,890.00	3,890.00

Ah Lim Company