

KA KA 9670 1127

BLK 22 WOODLANDS LINK
#04-30 WOODLANDS EAST
INDUSTRIAL ESTATE
SINGAPORE 738734
TEL: 63409432

Company Registration No: 33407432E



Company Address: No 22 Woodlands Link #04-30 Singapore 738734

VEHICLE NO : FBE9684S

VEHICLE CHASIS : PMY5PV100A0032902

VEHICLE MAKE & MODEL : YAMAHA RXZ 135

REGISTRATION YEA: 2010

QUOTATION SUMMARY

CLAIM DETAIL : PARTS					
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	SURVEYOR RECOMMENDATION
1	Speedometer	1	\$ 900.00	500 \$ 900.00	cra
2	Switch	1	\$ 135.00	85 \$ 135.00	cra
3	Fork Set	1	\$ 250.00	/ \$ 250.00	bt
4	Head Cowl	1	\$ 130.00	/ \$ 130.00	cra
5	Headlight	1	\$ 89.00	/ \$ 89.00	cra
6	Signal Light Set	1	\$ 75.00	/ \$ 75.00	cra
7	Bubble Head	1	\$ 53.35	/ \$ 53.35	bt
8	Headlight Cover	1	\$ 69.00	/ \$ 69.00	bt
9	Crown	1	\$ 255.00	/ \$ 255.00	bt
10	Handlebar	1	\$ 175.00	/ \$ 175.00	bt
11	Mudguard	1	\$ 68.00	/ \$ 68.00	cra
12	Front brake Disc	1	\$ 77.00	X \$ 77.00	Xnn
13	Headlight Stay Bar	1	\$ 68.00	/ \$ 68.00	bt
14	T Fork	1	\$ 174.00	/ \$ 174.00	bt
15	Mirror set	1	\$ 50.00	/ \$ 50.00	dis
16	Horn	1	\$ 59.00	/ \$ 59.00	bt
17	Wheel Shaft	1	\$ 59.00	/ \$ 59.00	bt
18	Throttle Cable	1	\$ 33.00	X \$ 33.00	Xnn
19	Speedometer Cable	1	\$ 33.00	/ \$ 33.00	bt
20	Footrest Assy Set	1	\$ 220.00	X \$ 220.00	Xnn
21	Fairing	1	\$ 250.00	X \$ 250.00	Xnn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL PRICE \$3,222.35
LESS 10% \$ 322.24
SUB TOTAL PRICE \$2,900.12

2192.35
10%
1973.11

Hp 90010068
4 days

CLAIM DETAIL : ESSENTIAL PARTS					
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	SURVEYOR RECOMMENDATION
1	Engine Oil	1	\$ 55.00	\$ 55.00	Xm
2	Clutch Gasket	1	\$ 25.00	\$ 25.00	Xnn
3	Side panel Original Decal	1	\$ 250.00	\$ 250.00	Xnn
4	Missing screws	12	\$ 5.00	\$ 60.00	20
5	Wheel Shaft Nut	1	\$ 12.90	\$ 12.90	\$pec
6	Cone Bearing Set	1	\$ 65.00	\$ 65.00	new
TOTAL				\$ 467.90	

97.90

20/10/21 @ 430
Resurvey after repair
1973.11

CLAIM DETAILS : LABOUR/SPECIALIST SERVICES			
S/N	DESCRIPTION	TOTAL S/NETT	SURVEYOR RECOMMENDATION
1	Labour for dismantling/installing	\$ 520.00	250
2	Rewiring specialist	\$ 250.00	30
3	Rim Press	\$ 180.00	80
4	Engine Case Repair	\$ 350.00	Xnn
TOTAL		\$1,300.00	360

97.90
360.00
3431.00
20%
1944.86

ESTIMATE REPORT

L/S - \$1,950