

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 9684S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SPEEDOMETER	CRACKED	900.00	500.00
1	SWITCH	CRACKED	135.00	85.00
1	FORK SET	BENT	250.00	250.00
1	HEAD COWL	CRACKED	130.00	130.00
1	HEADLIGHT	CRACKED	89.00	89.00
1	SIGNAL LIGHT SET	CRACKED	75.00	75.00
1	BUBBLE HEAD	BENT	53.35	53.35
1	HEADLIGHT COVER	CRACKED	69.00	69.00
1	CROWN	BENT	255.00	255.00
1	HANDLEBAR	BENT	175.00	175.00
1	MUDGUARD	CRACKED	68.00	68.00
1	FRONT BRAKE DISC	NOT NECESSARY	77.00	-
1	HEADLIGHT STAY BAR	BENT	68.00	68.00
1	T FORK	BENT	174.00	174.00
1	MIRROR SET	DISTORTED	50.00	50.00
1	HORN	BENT	59.00	59.00
1	WHEEL SHAFT	BENT	59.00	59.00
1	THROTTLE CABLE	NOT NECESSARY	33.00	-
1	SPEEDOMETER CABLE	BENT	33.00	33.00
1	FOOTREST ASSY SET	NOT NECESSARY	220.00	-
1	FAIRING	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-322.24	-219.24
			2,900.11	1,973.11
	SPECIAL NETT ITEMS			
1	ENGINE OIL (SN)	NOT NECESSARY	55.00	-
1	CLUTCH GASKET (SN)	NOT NECESSARY	25.00	-
1	SIDE PANEL ORIGINAL DECAL (SN)	NOT NECESSARY	250.00	-
12	MISSING SCREWS @\$5.00 (SN)	NECESSARY	60.00	20.00
1	WHEEL SHAFT NUT (SN)	NECESSARY	12.90	12.90

Report Ref No. CS/AGI21010715/Rtf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,950.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	CONE BEARING SET (SN)	NECESSARY	65.00	65.00
			467.90	97.90
	<u>LABOUR</u>			
	LABOUR FOR DISMANTLING/INSTALLING.		520.00	250.00
	REWIRING SPECILIST.		250.00	30.00
	RIMS PRESS.		180.00	80.00
	ENGINE CASE REPAIR.	NOT NECESSARY	350.00	-
			1,300.00	360.00
	GRAND TOTAL		4,668.01	2,431.01

Report Ref No. CS/AGI21010715/Rtf3n2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

JE. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.