

(08/11/13) wef

ASS. REC. BY: John

REF:

CS/NC21010718/R113

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBR 6653Hat Workshop m/s E2 MOTOR LLPof 31, WINDMILLS CLOSE # 05-21

Insured:

NSL

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBR 6653H

Yr Regn:

/

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: in order / Jammed / Leaked / Burnt orBrake: in order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-14

R:

140/60-14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

31/08/21

D.O.I.

19/10/21

Survey held at

E2 MOTOR LLPDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS \$☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

EZ Motor LLP

31 Woodlands Close, Woodlands Horizon #05-21, Singapore-737855

Tel : +65 9007 7390

Email : sales@ezmotorsg.com

Company Reg No : T21LL0760G

REPAIR ESTIMATE

No: MT/1143037-002

NTUC INCOME INSURANCE CO-OPERATIVE LTD.

75 BRAS BASAH ROAD,

INCOME CENTRE

SINGAPORE 189557

TEL: +65 6430 7899 N

FAX: +65 62244174

ATTN TO: MOTOR CLAIMS DEPT

Your Ref :

Our Ref : FBR6653H

Date : 19/10/2021

Page : 1 OF 2

ITEM	DESCRIPTION	QTY	U/PRICE S\$	TOTAL S\$
------	-------------	-----	-------------	-----------

THIRD PARTY CLAIM – REPAIR ESTIMATE FOR FBR6653H

TRAFFIC ACCIDENT ON 31/08/2021 INVOLVING FBR6653H AND SLR3369E

AT WOODLANDS DRIVE 72 TOWARDS WOODLANDS AVE 7

PARTS REQUIRED:

1. Front fender rear <i>cm</i>	1	\$ 30	\$ 30
2. Position cable + Bulb <i>?</i>	1	\$ 50	\$ 50
3. Mirror <i>X</i>	1	\$ 30	\$ 30
4. Inner Plastic <i>cut</i>	1	\$ 50	\$ 50
5. Compartment Cover <i>cut</i>	1	\$ 20	\$ 20
6. Fork Assembly <i>bt</i>	1	\$ 400	\$ 400
7. Front Wheel Axle <i>bt</i>	1	\$ 30	\$ 30
8. Cover set <i>?</i>	1	\$ 400	\$ 400
9. Brake Lever <i>X</i>	1	\$ 30	\$ 30
10. Bar End <i>X</i>	1	\$ 15	\$ 15
11. Left Bottom Panel <i>?</i>	1	\$ 40	\$ 40
12. Steering Cone Set <i>na</i>	1	\$ 70	\$ 70
13. Horn <i>bt</i>	1	\$ 30	\$ 70
14. Labour	3 days	\$ 380	\$ 380 250

Total Repair Cost

\$ 1645 . 00

EZ Motor LLP

31 Woodlands Close, Woodlands Horizon #05-21, Singapore-737855

Tel : +65 9007 7390

Email : sales@ezmotorsg.com

Company Reg No : T21LL0760G

REPAIR ESTIMATE

No: MT/1143037-002

NTUC INCOME INSURANCE CO-OPERATIVE LTD.
75 BRAS BASAH ROAD,
INCOME CENTRE
SINGAPORE 189557
TEL: +65 6430 7899 N FAX: +65 62244174
ATTN TO: MOTOR CLAIMS DEPT

Your Ref :
Our Ref : FBR6653H
Date : 19/10/2021
Page : 2 OF 2

ITEM	DESCRIPTION	QTY	U/PRICE S\$	TOTAL S\$
------	-------------	-----	-------------	-----------

Note:

1. Any discrepancy to be reported within 14 days otherwise considered correct
2. This estimate is based on visible damage only, should any hidden parts and / or labour charge required during work in progress, it will be notified accordingly.
3. Price quoted is subjected to 7% GST.

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
3 days
P/P
19/10/21 P1350
Resy before repair