

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: SLF5402S
Make and model: Toyota Axio
Chassis: NKE1657135035

Estimate

Qty Spare parts

- 1 Front bumper
- 1 Front bumper RH side retainer
- 1 Front bumper LH side retainer
- 1 LH headlamp assy
- 1 Front LH fender
- 1 Front LH fender "Hybrid" emblem
- 1 Front LH fender splash shield
- 1 Front LH shock absorber
- 1 Front LH wheel bearing
- 1 Front LH lower arm
- 1 Front LH lower arm ball joint
- 1 Front LH knuckle arm
- 1 Front LH tie rod end
- 1 Steering rack and pinion
- 1 Front LH side mirror assy
- 1 Front LH door
- 1 Front LH door frame black tape
- 1 Front LH door frame black tape (vertical)

2016

\$ 570.00	1,333.65	DDV ✓
\$ 45.00	95.50	} NECV
\$ 45.00	95.50	
\$ 825.00	1,021.80	BRV ✓
\$ 595.20	892.30	DDV ✓
\$ 162.00	78.40	NECV ✓
	381.80	TNV ✓
	721.40	} NDX
	122.30	
	602.10	
	215.80	
	597.80	
	156.30	
	1,645.30	
	1,014.60	
\$ 1,100.00 ✓	1,379.50	DDV ✓
	78.00	NECV ✓
	69.00	NECV ✓

\$ 3,567.60 10,501.05
-25% \$ 891.90 1,050.11
\$ 2,675.70 9,450.95

Qty Spare parts

- 1 Front LH sport rim
- 1 Front LH tyre
- 1set Front bumper clips
- 1set Front LH fender splash shield clips
- 1set Front LH door inner trim board clips
- 1 Brake fluid

local repair

\$ 200.00	850.00	R x AIT
\$ 30.00	320.00	NDX
\$ 30.00	70.00	NECV
\$ 30.00	60.00	NECV
\$ 30.00	60.00	NNX
\$ 70.00	70.00	NNX
260.00		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00 1,000.00

Spray painting on affected panels	\$ 600.00	1,000.00
Check wiring and lighting system	\$	70.00 NNX
Apply rust coating chemical on affected panels	\$	50.00 NNX
Remove and replace front LH undercarriage parts to assist repair	\$	220.00 NNX
Conduct and adjust wheel alignment system	\$	100.00 NNX
Remove and reinstall front LH door inner components to new door	\$ 80.00	100.00 NEC ✓
Refocus and adjust headlamps assy	\$	60.00 NNX
	1200.00	
Total:	\$	13,480.95

19/10/2021
 1415 hrs
 TCU in line
 Repair days 5
 Lump sum repair

Parts	2675.70
SN	260.00
Labour	1200.00
	4135.70
@ 20%	827.14
	3308.56

LS 3300/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TCU in line
 20/10/2021