

*Ster (KK)
 20/10/21, 11.30am*



*WL PL
 P/P
 My BLSM
 5 days*

Quotation
 Non binding - Preview

Page	1/2
Document no.	18-10-2021
Document date	5211043754
Customer no.	197800490N
Customer GST-ID	30001
Dealer	2021039610/ 1
Job order number	18-10-2021
Job order date	SHU SHI TANG
Service Advisor	

License plate	Model code	First registration	VIN	Model	Mileage
SMU8771R	5T13NZC0	01-09-2020	WVGZZZ1TZKW072608	Touran Comfortline 1.4 TSI 110kW DSG	13,479

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
D 169300M2	1k Window Adhesive ✓ APC	2	pcs.	51.30	#1	102.60	109.78
D 00940104	All Purpose Cleaner ✓ APC	1	pcs.	97.65	#1	97.65	104.49
D 00920002	Primer ✓ APC	1	pcs.	28.52	#1	28.52	30.52
D 181802M1	Activator For Precoated W ✓ APC	1	pcs.	26.23	#1	26.23	28.07
D 00950025	Applicator ✓ APC	2	pcs.	10.47	#1	20.94	22.41
5TA827025Q	Heckklappe ✓ APC	1	pcs.	2,305.10	#1	2,305.10	2,466.46
5TA827939 041	REAR BOOT LID ✓ APC (phth)		pcs.	267.95	#1	267.95	286.71
5TA827940 041	Spoiler Satin Black REAR W/SCREEN SIDE TRIM LH		pcs.	280.34	#1	280.34	299.96
5TA827940 041	Spoiler Satin Black REAR W/SCREEN SIDE TRIM RH ✓ APC (phth)	1	pcs.				
8D0853419D	Packing Adhesive ✓ APC	1	pcs.	30.60	#1	30.60	32.74
WHT007341	RR NUMBER PLATE PACKING						
5TA827505D	Riveted Cap Nut ✓ APC	2	pcs.	2.50	#1	5.00	5.35
5TA827505D	Hood Latch ✓ X nn	1	pcs.	175.26	#1	175.26	187.53
5TA853630A DPJ	BOOT LID LOCK						
5TA853630A DPJ	Vw Sign Black/Bright Chro ✓ APC	1	pcs.	108.68	#1	108.68	116.29
5TA853687 2ZZ	Inscription Bright Chrome ✓ APC	1	pcs.	74.51	#1	74.51	79.73
3CN945087	NAME PLATE - TOURAN						
3CN945087	Additional Brake Light Wi ✓ APC (phth)	1	pcs.	229.42	#1	229.42	245.48
5TA807417 GRU	3RD BRAKELIGHT						
5TA807568A 9B9	Cover For Bumper Primed ✓ APC	1	pcs.	1,443.25	#1	1,443.25	1,544.28
5TA807305	Spoiler Satin Black ✓ CUT	1	pcs.	332.69	#1	332.69	355.98
5TA807305	Bumper ✓ APC	1	pcs.	552.19	#1	552.19	590.84
5TA807863	REINFORCEMENT						
5TA807863	Attachment Strip ✓ X nn	1	pcs.	65.63	#1	65.63	70.22
5TA807453	BUMPER CTR BRACKET						
5TA807453	Guide Piece ✓ X nn	1	pcs.	42.63	#1	42.63	45.61
5TA807454	LHR BUMPER BRACKET (UPPER)						
5TA807454	Guide Piece ✓ X nn	1	pcs.	42.63	#1	42.63	45.61
5TA807393	RHR BUMPER BRACKET (UPPER)						
5TA807393	Guide Piece ✓ X nn	1	pcs.	34.85	#1	34.85	37.29
5TA807394	LHR BUMPER BRACKET (SIDE)						
5TA807394	Guide Piece ✓ X nn	1	pcs.	34.85	#1	34.85	37.29
	RHR BUMPER BRACKET (SIDE)						
	LABOUR	82	pcs.	840.00	#1 1680	4,200.00	4,494.00
	SPRAY PAINT	52	pcs.	800.00	#1 1600	4,000.00	4,280.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1 420	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	REVERSE SENSOR	1	pcs.	400.00	#1 9	400.00	X nn 428.00

Quotation
 Non binding - Preview

Page	2/2
Document no.	18-10-2021
Document date	5211043754
Customer no.	197800490N
Customer GST-ID	30001
Dealer	2021039610/ 1
Job order number	18-10-2021
Job order date	SHU SHI TANG
Service Advisor	

License plate	Model code	First registration	VIN	Model	Mileage
SMU8771R	ST13NZC0	01-09-2020	WVGZZ1TZKW072608	Touran Comfortline 1.4 I TSI 110kW DSG	13,479

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
EQ DIRECT SETTLEMENT DOA: 15/10/2021 TP VEH: SJR2398B SURVEY BY:							

Quotation valid till 25-10-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	16,811.52	7%	1,230.01	17,571.52	18,801.53
Total	760.00	16,811.52		1,230.01	17,571.52	18,801.53

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: