

Our Job Ref No : 305491085
Date : 20/10/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
58 Loyang Drive Singapore 508989
Fax: 6548 8158

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SH 6080L

Fax :

Date of Accident : 17.10.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- GBB7601K
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$938.16
 - (b) Labour Charges \$641.00
 - Total for Part-By-Part Repair Cost \$1,579.16**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 29/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

TS

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

400.00 350

2 SPRAY PAINTING

New

300.00 250

3 R/I REVERSE SENSORS

New

120.00 30

Gross Labour Cost (S\$)

820.00

ComfortDelGro Engineering Pte Ltd/SH6080L/18/10/2021 11:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan@LKKAuto.com

82235769

18/10/21 1715

P/P bfr paint photo

2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

B

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Oct 2021)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SH6080L/18/10/2021 11:31
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL / Det
2	1		*REAR BUMPER SIDE BRACKET LH	20.00	0.00	*138.10 FL / nec
3	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	*41.45 FL / scv
4	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL / nec
5	1		*REAR BUMPER MAT	0.00	0.00	*50.00 FL / nec
6	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL / scv

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 1,162.20
- List Item Discount on L Items (\$\$) 222.44

Total Parts (\$\$) 939.76

ComfortDelGro Engineering Pte Ltd/SH6080L/18/10/2021 11:31. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305491085
 REGN NO : SH 6080L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 29.04.2021
 DATE/TIME IN : 18.10.2021 08:40
 ACCIDENT DATE : 17.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002 04-01-0104-2531-G	REAR BUMPER SIDE BRKT LH	1	138.10	20.00	110.48
0003 04-01-0104-0851-G	REAR BUMPER REFLECTOR LH	1	41.45	20.00	33.16
0004 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	20.00	20.00	16.00
0005 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00	2.00	50.00
0006 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00

SUB-TOTAL : 938.16

JOB NATURE

0000 PB	PANEL BEATING-SH 6080L	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	R/I REVERSE SENSORS	30.00
0003 20-05	TP MERIMEN	11.00

SUB-TOTAL : 641.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305491085
REGN NO : SH 6080L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 29.04.2021
DATE/TIME IN : 18.10.2021 08:4
ACCIDENT DATE : 17.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,579.16


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : _____

AUTHORISED : YES / NO