



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2107560

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 03/11/2021
Reference CS3/GRB21010730/Gvf3e2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 9499D
Insured Veh. SMP 8086L
Claim No. MFL2021D0004602
Policy No. D21MFL0000447
Accident Date 16/10/2021
Inspection Date 25/10/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 25.10.2021 05.00pm	
- Dismantle Inspection 26.10.2021 11.15am	
- After Repair Inspection 01.11.2021 03.49pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM