



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21010731/Avf3n2	
			Date: 25/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLF 7924P	Veh. Inspected	SMM 8080T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102935/THE	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	19/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA 200	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD1173432N034528	Colour	GREY
	Odometer	204084 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/40 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/09/2021	Inspection Date	19/10/2021
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	