



# 進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No: A05041/2001E

GST Reg. NO: 20-0105041-E

MR MING XIN TRADING (1997)  
8A ADMIRALTY STREET  
#04-17 FOOD EXCHANGE @ ADMIRALTY  
SINGAPORE 757437

POLICY NO : THIRD PARTY CLAIM  
YOUR REF : GBK 6680 R (LONPAC)  
OUR REF : TP 6323  
VEHICLE NO : GBG 9399 E  
MAKE/MODEL : TOYOTA PROACE  
DATE OF ACCIDENT : 15.10.21

1997.25  
320.00  
1750.00  
3480.00  
7547.25

20%  
6037.80  
45-\$6,050

## SURVEY BY

DATE : 18.10.21

|       |                                   |        |          |  |  |     |            |
|-------|-----------------------------------|--------|----------|--|--|-----|------------|
| 1 PC  | FRONT BUMPER                      | de/    |          |  |  | \$S | 950.00     |
| 1 PC  | FRONT BUMPER GRILLE               | scu/   |          |  |  |     | 350.00     |
| 1 PC  | FRONT BUMPER GRILLE LOWER GARNISH | scu/   |          |  |  |     | 180.00 X   |
| 2 PCS | FRONT BUMPER SIDE RETAINERS       | xan    | 70.00    |  |  |     | 140.00 X   |
| 2 PCS | REAR DOOR                         | repair | 1,350.00 |  |  |     | 2,700.00 X |
| 2 PCS | REAR DOOR INNER LOCK              | xan    | 180.00   |  |  |     | 360.00 X   |
| 1 PC  | REAR DOOR EMBLEM                  | ne/    |          |  |  |     | 68.00      |
| 1 PC  | REAR DOOR "TOYOTA" EMBLEM         | ne/    |          |  |  |     | 60.00      |
| 1 PC  | REAR DOOR "PROACE" EMBLEM         | ne/    |          |  |  |     | 75.00      |
| 2 PCS | REAR DOOR NO. PLATE LAMP          | xan    | 125.00   |  |  |     | 250.00 X   |
| 1 PC  | REAR BUMPER                       | de/    |          |  |  |     | 780.00     |
| 2 PCS | REAR BUMPER SIDE RETAINERS        | xan    | 65.00    |  |  |     | 130.00 X   |
| 1 PC  | REAR BUMPER REINFORCEMENT         | bt/    |          |  |  |     | 380.00     |
| 1 PC  | REAR END OUTER PANEL              | xan    |          |  |  |     | 450.00 X   |

6 days  
L/S  
21/10/21  
P HIO  
Roj after repair

|        |                            |     |       |  |  |  |  |
|--------|----------------------------|-----|-------|--|--|--|--|
| 1 SET  | NO. PLATE                  |     | 45.00 |  |  |  |  |
| 10 PCS | FRONT BUMPER CLIPS         | bt/ | 3.50  |  |  |  |  |
| 1 PC   | REAR DOOR "70KM/H" STICKER | ne/ |       |  |  |  |  |
| 12 PCS | REAR BUMPER CLIPS          | ne/ | 3.50  |  |  |  |  |
| 1 PC   | REVERSE CAMERA             | xan |       |  |  |  |  |
| 1 SET  | REVERSE SENSOR             | ne/ |       |  |  |  |  |

|     |          |
|-----|----------|
| \$S | 6,873.00 |
| \$S | 1,718.25 |
| \$S | 5,154.75 |
| \$S | 35       |
| \$S | 90.00    |
| \$S | 35.00    |
| \$S | 20.00    |
| \$S | 30       |
| \$S | 42.00    |
| \$S | 300.00 X |
| \$S | 200      |
| \$S | 250.00   |
| \$S | 737.00   |

2663  
258  
1997.25  
S/ NETTY  
320

- TO DISMANTLE AND REFIX REVERSE CAMERA Xn1
- TO TRANSFER REAR DOOR FITTINGS
- TO REMOVE AND REFIX REVERSE SENSOR
- TO REMOVE AND REFIX REAR UPHOLSTERY Xn1
- TO CHECK WIRING FUNCTION
- TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL

|     |              |
|-----|--------------|
| \$  | 150.00 X     |
| 80  | 200.00       |
| 60  | 100.00       |
|     | 100.00 X     |
|     | 60.00 X      |
|     | 100.00 X     |
|     | 1,000.00 700 |
|     | 1,200.00 750 |
| \$S | 8,801.75     |

1750

LABOUR CHARGES

TO PUTTY AND SPRAY PAINTING CHARGES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SIN DOLLARS: EIGHT THOUSAND EIGHT HUNDRED ONE AND CENTS SEVENTY-FIVE ONLY

YOUR FAITHFULLY,

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700  
Tel: 6219 2096 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CYS AUTOMOBILE SERVICES PTE LTD