

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

XIAO PENG
BLK 776 YISHUN AVE 2 #10-1595
SINGAPORE 760776

TP Chim.
Denise.

Contact : 92978923

TAX INVOICE

Repair Code : CLM15331
Date in : 18/10/2021
Vehicle Num. : SME5833A
Model : HONDA FREED HYBRID 1.5G AUTO
Chassis/Eng# : GB71073721/LEB5608509

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT AIRCON ALUMINIUM PIPE <i>Ne Nec</i>	1	425.00	425.00
FRONT BUMPER (MODURO X) <i>Distorted</i>	1	3105.00	<i>1600(SN)</i> 3,105.00
FRONT BUMPER LOWER GRILLE (MODURO X)	1	298.00	✓ 298.00
FRONT BUMPER REINFORCEMENT <i>Dented.</i>	1	398.00	✓ 398.00
FRONT BUMPER RH FOGLAMP (LED) <i>cracked</i>	1	425.00	✓ 425.00
FRONT BUMPER SIDE RETAINER L/R <i>RH Dented</i>	2	25.00	<i>25</i> 50.00
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	35.00	✓ 35.00
FRONT GRILLE (MODURO X) <i>cracked</i>	1	901.00	✓ 901.00
FRONT HEADLAMP L/R <i>RH cracked</i>	2	1458.20	<i>1458.20</i> 2,916.40
FRONT HEADLAMP LOWER BRACKET L/R <i>RH cracked</i>	2	36.50	<i>36.50</i> 73.00
FRONT RH FENDER 'HYBRID' EMBLEM <i>:New</i>	1	68.80	✓ 68.80
FRONT RH FENDER INNER PANEL <i>Repair</i>	1	533.20	✓ 533.20
FRONT RH FENDER INNER SHIELD <i>torn</i>	1	120.40	✓ 120.40
FRONT SUPPORT PANEL <i>new</i>	1	752.60	✓ 752.60
Subtotal before discount			10,101.40
Percentage discount 20%			2,020.28
Sub-total 1			8,081.12
FRONT BUMPER CLIPS - SET <i>Nec</i>	1	50.00	<i>30</i> 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-177 #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

XIAO PENG
BLK 776 YISHUN AVE 2 #10-1595
SINGAPORE 760776

Contact : 92978923

TAX INVOICE

Repair Code : CLM15331

Date in : 18/10/2021

Vehicle Num. : SME5833A

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71073721/LEB5608509

FRONT BUMPER NUMBER PLATE	1	25.00	+	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	100.00	+	100.00
FRONT BUMPER REINFORCEMENT BAR	1	450.00	+	450.00
FRONT BUMPER SIDE LED LAMP RH	1	250.00	120.	250.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	1	50.00	30.	50.00
RADIATOR COOLANT	1	80.00	+	80.00
Subtotal before discount				1,005.00
Percentage discount 0%				0.00
Sub-total 2				1,005.00
Parts-total				9,086.12

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,300.00

11,386.12

*** This is a computer-generated document which requires no signature.***

page 2

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5652.72
4/5: 4.5K
03Days
4.5K