

Our Job Ref No : 305491373

Date : 27/10/21

ComfortDelGro Engineering Pte Ltd
50 Loyang Drive, Singapore 508989
Fax: 6548 8158

FINALIZATION FORM

To : LKK

Fax

Attn : Mr THEVAN

Vehicle Reg No. SHD3699Z CTPL

19/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows -

1. The repair job shall bill to: AIG SJH8421E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$3,250.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : thavan

Date : 29/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD3699Z

Make : HYUNDAI

Model : I-40

Date: 19/10/2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20 ✓/cut
10	FRT BUMPER CLIPS			\$22.00 ✓/nrc
1	FRT BUMPER BRACKET TOP RH			\$44.80 ✓/nrc
1	FRT BUMPER GRILLE RH			\$187.20 X SVC
1	FRT FENDER RH			\$663.00 BT
1	FRT FENDER SHIELD RH			\$174.90 X SVC
1	HEADLAMP RH			\$1,800.00 ✓/scr
1	FRT BUMPER REINFORCEMENT			SVC \$588.40 X
1	FRT BUMPER SIDE BRACKET RH			\$24.60 ✓/nrc
1	HEADLMAP SUPPORT PANEL ASSY			SVC \$907.40 X ✓
SUB TOTAL				\$5,464.50
LESS 20%				\$1,092.90
DISCOUNTED TOTAL				\$4,371.60
FRONT FENDER ADVERTISEMENT LOGO RH				\$100.00
				\$100.00 Net ✓/nrc
Labour Charge				
PANEL BEATING				\$900.00 560
SPRAY PAINTING CHARGE				\$800.00 500
TUFF KOTE				\$60.00 20
WIRING CHARGE				\$60.00 20 ✓
TOTAL LABOUR				\$1,820.00
ESTIMATE TOTAL				\$6,291.60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thru an @Chhayto.com
82235769
19/10/21 1615
L/S after repair photo
2 3 days up

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: