

ASS. REC. BY: Tang JH

REF: CS / ALG 21010749 / H53

ASSIGNMENT

CoE 2022 April

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 41400 **1300**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FB55323B Yr Regn: 2007 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha Spark 135 c.c. 135

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 34331 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 5YP205115

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: P01 90R17

R: P01 90R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 20/00/21

Survey held at TSL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 41000.
	Inform m/s repair limit 900.
	RED: 6729.50;88%
	FINALISE AT 900,

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.S. ()

Days Of Repair: **4**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

FBB5323B Yamaha Jupiter

			Estimated Parts Price	
No	Qty	Parts Description		
1	1 set	Front handle bar	\$ 275.00	X un
2	2	Front handle bar grip with balancer	\$ 45.00	LH X un RH X un
3	1	Front headlamp assy	\$ 285.00	X
4	1	Front headlamp stay bracket	\$ 65.00	X
5	1	Front headlamp top cowling	\$ 155.00	X
6	1	Front headlamp outer cowling	\$ 225.00	X
7	1	Front left side top fairing	\$ 295.00	X
8	1	Front right side top fairing	\$ 295.00	cut
9	1	Front left side lower fairing	\$ 395.00	X un
10	1	Front right side lower fairing	\$ 395.00	cut
11	1	Front left side lamp	\$ 125.00	X un
12	1	Front right side lamp	\$ 125.00	cut
13	1	Front left side mirror	\$ 65.00	X un
14	1	Front right side mirror	\$ 65.00	cut
15	1	Front fender	\$ 105.00	cut
16	1 set	Front fork assy	\$ 1,030.00	X SN 120 Shifted
17	2	Front fork stem	\$ 45.00	X un
18	1	Front brake lever	\$ 65.00	X un
19	1	Front clutch lever	\$ 65.00	cut
20	1	Front right foot brake	\$ 55.00	bt
21	1	Front right foot rest	\$ 55.00	bt
22	1	Front left gear selector	\$ 55.00	X
23	1	Front left foot rest	\$ 55.00	X
24	1	Front meter assy	\$ 295.00	X
25	1	Front wheel rim	\$ 450.00	X un
26	1	Front wheel shaft	\$ 95.00	X
27	1	Front brake caliper	\$ 175.00	X
28	1	Front brake reservoir	\$ 65.00	X
29	1	Rear left side fairing	\$ 195.00	X
30	1	Rear right side fairing	\$ 195.00	cut
31	1	Rear exhaust muffler assy	\$ 625.00	X un
32	1	Rear exhaust muffler chrome protector	\$ 145.00	del
33	1	Rear left pillion foot rest	\$ 55.00	X
34	1	Rear right pillion foot rest	\$ 55.00	X
35	1	Rear left side cover	\$ 35.00	X
36	1	Rear right side cover	\$ 35.00	X
37	1	Side stand	\$ 45.00	X
			\$ 6,805.00	1522.50
less 10%			\$ 680.50	1370.25
			\$ 6,124.50	

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

FBB5323B Yamaha Jupiter

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Front no plate	\$ 35.00 X
2	1	ERP IU	\$ 180.00 X
3	1	ERP IU bracket	\$ 35.00 X
4	2	Front fork oil	\$ 60.00 X
5	1	Rear no plate	\$ 35.00 X
6	1	Rear box assy	\$ 300.00 <i>cut</i>
7	1	Rear box bracket	\$ 200.00 X <i>un</i>
			\$ 845.00 <i>300</i>

Total parts

\$ 6,969.50

Labour - \$300 200
wiring - \$60 30
Spray painting - \$300 200
430

7629.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) not be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1370.25

300

430

2100.25

20% 1680.20

Repair limit \$900

CoR 4/5 \$900

4 days

Tanpin 97495749

wp- 20/10/21 @ 5pm

4/5 Resurvey after repair
Tanpin @ 11h30 to 12h00