

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000528**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 18-OCT-2021
 MAKE : HONDA
 MODEL : STREAM 1.8 A
 CHASSIS NO : RN61036962
 ENGINE NO : R18A1741790
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 3

SDH9588Y
LIM BOK CHUAN
 BLK 19
 BEDOK SOUTH ROAD
 #07-23
 SINGAPORE,
 SINGAPORE 460019
 CONTACT NO : 97110292

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
<u>LIST ITEM</u>			
1	TAILGATE	991.20	
1	TAILGATE INNER TRIM	170.30	
1	TAILGATE INNER TRIM HANDLE	20.70	
1	TAILGATE HINGE RH	52.30	
1	TAILGATE HINGE LH	52.30	
1	TAILGATE EMBLEM LOGO "HONDA"	24.70	
1	TAILGATE EMBLEM "STREAM"	36.00	
1	TAILGATE LOCK TOP	124.50	
1	TAILGATE LOCK BOTTOM	27.00	
1	TAILGATE WINDSCREEN MOULDING	118.00	
1	TAILGATE WEATHER STRIP	137.50	
1	TAILGATE OUTER GARNISH	183.50	
1	TAIL LAMP RH	459.20	
1	TAIL LAMP LH	459.20	
1	REAR BUMPER	704.90	
1	REAR BUMPER SIDE RETAINER RH	24.00	
1	REAR BUMPER SIDE RETAINER LH	24.00	
1	REAR SMART BUZZER	85.00	
1	REAR BUMPER TOWING COVER	18.00	
1	REAR END PANEL OUTER	346.80	
1	REAR END PANEL INNER	158.10	
1	REAR END PANEL TOP GARNISH	140.90	
1	FLOOR PANEL	1,190.50	
1	FLOOR PANEL TOP BOARD	145.20	
1	REAR EXTENTION PANEL RH	562.50	
1	TOOLS TOP BOX	129.50	
1	SPARE TYRE BRACKET	165.90	

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000528**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 18-OCT-2021
MAKE : HONDA
MODEL : STREAM 1.8 A
CHASSIS NO : RN61036962
ENGINE NO : R18A1741790
SERVICE ADVISOR : HAZEL
PAGE : 2 OF 3

SDH9588Y

LIM BOK CHUAN

BLK 19
BEDOK SOUTH ROAD
#07-23
SINGAPORE,
SINGAPORE 460019
CONTACT NO : 97110292

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR TOOLS COMPARTMENT	249.80	
1	TAILGATE CABLE	75.00	
1	TAILGATE ABSORBER RH	132.90	
1	TAILGATE ABSORBER LH	132.90	
1	REAR AXEL	0.00	
1	EXHAUST	588.40	
1	EXHAUST ALUMINIUM HEAT SHIELD	60.50	
1	REAR FENDER RH	977.20	
1	REAR FENDER LH	977.20	
Sub Total		9,745.60	0.00

SPECIAL NETT

10	REAR BUMPER CLIPS	50.00	
1	TAILGATE SEALANT	50.00	
1	REVERSE CAMERA	380.00	
1	REAR END PANEL SEALANT	50.00	
1	WINDSCREEN SEALANT	50.00	
10	REAR END PANEL TOP GARNISH CLIPS	50.00	
Sub Total		630.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,600.00
---	--	----------

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000528**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 18-OCT-2021
MAKE : HONDA
MODEL : STREAM 1.8 A
CHASSIS NO : RN61036962
ENGINE NO : R18A1741790
SERVICE ADVISOR : HAZEL
PAGE : 3 OF 3

SDH9588Y

LIM BOK CHUAN

BLK 19
BEDOK SOUTH ROAD
#07-23
SINGAPORE,
SINGAPORE 460019
CONTACT NO : 97110292

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO SPRAY PAINT ON AFFECTED AREAS	1,600.00	
1	TO APPLY TUFF COAT ON AFFECTED AREAS	180.00	
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	250.00	
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	150.00	
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	200.00	
	Sub Total	3,980.00	0.00

SUB-TOTAL	14,355.60	0.00
GST - 7 %	1,004.89	0.00
TOTAL	15,360.49	0.00

ABWIN SERVICE PTE LTD

Prepared By