

ABWIN SERVICE PTE LTD
 7 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



ESTIMATED COST: HQQ000528

INSURANCE : AIG ASIA PACIFIC INSURANCE PTE. LTD.
DEPARTMENT : MOTOR CLAIM DEPARTMENT

VEHICLE NO: DH9588Y
DRIVER: LIM BOK CHUAN
PLATE: LK 19
ADDRESS: EDOK SOUTH ROAD
POSTCODE: 107-23
CITY: SINGAPORE
POSTAL CODE: SINGAPORE 460019
CONTACT NO: 97110292

DATE: 18-OCT-2021
MAKE: HONDA
MODEL: STREAM 1.8 A
CHASSIS NO: RN61036962
ENGINE NO: R18A1741790
SERVICE ADVISOR: HAZEL
PAGE: 1 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	TAILGATE	991.20	bt ✓
1	TAILGATE INNER TRIM	170.30	ana ✓
1	TAILGATE INNER TRIM HANDLE	20.70	dl ✓
1	TAILGATE HINGE RH	52.30	XK ✓
1	TAILGATE HINGE LH	52.30	XK ✓
1	TAILGATE EMBLEM LOGO "HONDA"	24.70	ana ✓
1	TAILGATE EMBLEM "STREAM"	36.00	ana ✓
1	TAILGATE LOCK TOP	124.50	bt ✓
1	TAILGATE LOCK BOTTOM	27.00	bt ✓
1	TAILGATE WINDSCREEN MOULDING	118.00	ana ✓
1	TAILGATE WEATHER STRIP	137.50	ana ✓
1	TAILGATE OUTER GARNISH	183.50	XK ✓
1	TAIL LAMP RH	459.20	XK ✓
1	TAIL LAMP LH	459.20	XK ✓
1	REAR BUMPER	704.90	dl ✓
1	REAR BUMPER SIDE RETAINER RH	24.00	XK ✓
1	REAR BUMPER SIDE RETAINER LH	24.00	XK ✓
1	REAR SMART BUZZER	85.00	XK ✓
1	REAR BUMPER TOWING COVER	18.00	dl ✓
1	REAR END PANEL OUTER	346.80	bt ✓
1	REAR END PANEL INNER	158.10	bt - photo ✓
1	REAR END PANEL TOP GARNISH	140.90	dl ✓
1	FLOOR PANEL	1,190.50	ana - photo ✓
1	FLOOR PANEL TOP BOARD	145.20	XK ✓
1	REAR EXTENTION PANEL RH	562.50	XK ✓
1	TOOLS TOP BOX	129.50	XK ✓
1	SPARE TYRE BRACKET	165.90	XK ✓

ESTIMATED COST: HQQ000528

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SDH9588Y
LIM BOK CHUAN
BLK 19
BEDOK SOUTH ROAD
#07-23
SINGAPORE,
SINGAPORE 460019
CONTACT NO : 97110292

DATE : 18-OCT-2021
MAKE : HONDA
MODEL : STREAM 1.8 A
CHASSIS NO : RN61036962
ENGINE NO : R18A1741790
SERVICE ADVISOR : HAZEL
PAGE : 2 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR TOOLS COMPARTMENT	249.80 X	} un
1	TAILGATE CABLE	75.00 X	
1	TAILGATE ABSORBER RH	132.90 X	
1	TAILGATE ABSORBER LH	132.90 X	
1	REAR AXEL	0.00 X	
1	EXHAUST	588.40 X	} un
1	EXHAUST ALUMINIUM HEAT SHIELD	60.50 X	
1	REAR FENDER RH	977.20 X	
1	REAR FENDER LH	977.20 X	
Sub Total		9,745.60	4728.80

SPECIAL NETT

10	REAR BUMPER CLIPS	50.00 30 NEC	} un
1	TAILGATE SEALANT	50.00 40 NEC	
1	REVERSE CAMERA	380.00 X un	
1	REAR END PANEL SEALANT	50.00 40 NEC	
1	WINDSCREEN SEALANT	50.00 ne	
10	REAR END PANEL TOP GARNISH CLIPS	50.00 20 un	} un
Sub Total		630.00	225

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,600.00 900	
---	--	-------------------------	--

0.00
200% 3783.04

1100

ABWIN SERVICE PTE LTD

7 KAKI BUKIT ROAD 4
01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000528**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

IDH9588Y
IM BOK CHUAN
BLK 19
BEDOK SOUTH ROAD
#07-23
SINGAPORE,
SINGAPORE 460019
CONTACT NO : 97110292

DATE : 18-OCT-2021
MAKE : HONDA
MODEL : STREAM 1.8 A
CHASSIS NO : RN61036962
ENGINE NO : R18A1741790
SERVICE ADVISOR : HAZEL
PAGE : 3 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO SPRAY PAINT ON AFFECTED AREAS	1,600.00	1000
1	TO APPLY TUFF COAT ON AFFECTED AREAS	180.00	40
1	TO DISMANTLE, REPLACE AND/OR REPAIR TAILGATE COMPONENTS	250.00	60
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE CAMERA & TESTING	150.00	50 2130
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	200.00	80
Sub Total		3,980.00	2330 0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 17495749
'up' 19/10/21 @ 445
Lumpsum Resumy after repair
Tanpin @ 11kants on
7 days.

SUB-TOTAL	14,355.60	0.00
GST - 7 %	1,004.89	0.00
TOTAL	15,360.49	0.00

ABWIN SERVICE PTE LTD

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**SUPPLEMENTARY: HQQ000529**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SDH9588Y
LIM BOK CHUAN
BLK 19
BEDOK SOUTH ROAD
#07-23
SINGAPORE,
SINGAPORE 460019
CONTACT NO : 97110292

DATE	:	20-OCT-2021
MAKE	:	HONDA
MODEL	:	STREAM 1.8 A
CHASSIS NO	:	RN61036962
ENGINE NO	:	R18A1741790
SERVICE ADVISOR	:	HAZEL
PAGE	:	1 OF 1

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FENDER INNER BOARD RH <i>ana</i>	0.00	\$ 245
1	FENDER INNER BOARD LH <i>ana</i>	0.00	\$ 245

Sub Total	0.00	0.00
------------------	-------------	-------------

Spare tyre lt ✓



\$ 380

870

25% - 696

3783.04

225

2330

696

7034.04

45856.00 #
07 days

SUB-TOTAL	0.00	0.00
GST - 7 %	0.00	0.00
TOTAL	0.00	0.00

ABWIN SERVICE PTE LTD