

01 Longpac
(IN) LKK.

No. : 32044

Date : 19-Oct-2021

Accident Date : 16-Oct-2021

Our Ref : 021429 / CARIN

PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

Not Authorized
Returning B4 paint
Ex ??

4-5 days

ESTIMATED COST OF REPAIR FOR MERCEDES BENZ CLA180 (1595CC)(2016) SNA174K
=====

1 pc	front no. plate base garnish	CM	53.00	—
1 pc	front bumper	CM	755.00	—
1 pc	o/s front bumper side grille	mi	25.00	—
1 pc	frt bumper centre lower grille	mi	85.00	—
1 pc	o/s front bumper nozzle cover]	mi	44.00	—
1 pc	o/s front bumper nozzle cover]			
	bracket			
1 pc	o/s front bumper nozzle cover	mi	5.50	—
	spring			
1 pc	o/s front bumper nozzle pump	mi	100.00	?
1 pc	o/s front bumper side bracket	mi	11.00	—
1 pc	front bumper tow cover	mi	35.00	—
1 pc	front bumper inner top bracket	CM	100.00	2
1 pc	front bumper inner sponge		100.00	?
1 pc	front bumper reinforcement		160.00	?
1 pc	front bumper logo	CM	36.00	—
1 pc	front bumper top seal	mi	22.00	—
1 pc	o/s front bumper parking	mi	100.00	x
	sensor - outer			
1 pc	o/s front bumper parking		100.00	?
	sensor - inner			
1 pc	o/s front bumper parking		100.00	?
	sensor lower - inner			
4 pcs	frt bumper parking sensor seal @ S\$ 3.90	mi	15.60	—
1 pc	frt bumper under cover		190.00	?
1 pc	radar sensor		620.00	?
1 pc	radar bracket		42.00	?

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Page : 2

No. : 32044

Our Ref : 021429

1 pc	front grille		410.00	✓
1 pc	front grille logo		73.00	✓
1 pc	front grille base logo		44.00	✓
2 pcs	front grille moulding LH&RH	@ S\$ 45.00	90.00	X
2 pcs	frt grille inner air reflector	@ S\$ 31.00	62.00	✓
	LH & RH			
1 pc	frt grille outer garnish		28.00	✓
1 pc	bonnet		810.00	X
1 pc	bonnet outer seal		22.00	X
1 pc	bonnet centre lock - lower		65.00	✓
1 pc	bonnet centre lock catch		30.00	✓
1 pc	front support panel		375.00	✓
1 pc	front support panel bracket		38.00	✓
1 pc	air intake duct		50.00	
1 pc	air intake inner hose			
1 pc	aircon condenser c/w cowling		540.00	X
1 pc	radiator		450.00	X
2 pcs	radiator top bracket bush	@ S\$ 15.50	31.00	X
2 pcs	radiator top bracket pin	@ S\$ 6.60	13.20	X
1 pc	radiator fan cowling c/w blade and motor		245.00	X
2 pcs	radiator air guide LH & RH	@ S\$ 32.00	64.00	✓
2 pcs	radiator lower bracket LH & RH	@ S\$ 20.00	40.00	✓
1 pc	turbo cooler		420.00	X
1 pc	turbo cooler air duct		50.00	X
2 pcs	headlamp assy LH & RH	@ \$1300.00	2,600.00	nl? ✓
			9,249.30	
Add 10% :			924.93	
			10,174.23	
1 pc	front number plate		40.00	sn ✓
1 pc	radiator coolant		48.00	sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 500

Con't Page 3 ...

金興(集)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (S Lines) Fax: 6458 3895

Our Ref : 021429

Page : 3

No. : 32044

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

RM 100.00 X

To putty and respray on affected
portions.

550.00 450/

To focus headlamps. To check front
wiring and lighting operation.

50.00 20/

Total : S\$11,762.23
=====

Singapore Dollars Eleven Thousand Seven Hundred
and Sixty Two and Cents Twenty Three Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.