



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21010758/Ktf3e2 Date: 02/12/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SNA 174K
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VP05/025051	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	19/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WDD1173422N343680	Colour	METALLIC BLACK
	Odometer	77798 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	CONTINENTAL	9 mm
	L/H Front Tyre	225/45 R18	CONTINENTAL	9 mm
	R/H Rear Tyre	225/45 R18	CONTINENTAL	9 mm
	L/H Rear Tyre	225/45 R18	CONTINENTAL	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/10/2021	Inspection Date	20/10/2021
	Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE MARKET VALUE IS S\$78,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days