

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

10/11/21

Mohammad Danial Fitri

Name : **Bin Mohd Shahril Disilva**
(86080176)

Accident Date : **15-Oct-21**

Vehicle No : **FBP8806G**

Vehicle Model : **Yamaha Aerox**
GDR155 CVT
ABS

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy <i>su</i>	\$ 980.00 <i>X</i>
1	Fork under bracket <i>su</i>	\$ 190.00 <i>X</i>
1	Front sport rim <i>11</i>	\$ 550.00 <i>X</i>
1	Front brake disc <i>11</i>	\$ 180.00 <i>X</i>
1	Front rim shaft <i>ACU</i>	\$ 52.00 <i>✓</i>
1	Front rim bearing <i>11</i>	\$ 48.00 <i>X</i>
1	Headlamp <i>one</i>	\$ 550.00 <i>✓</i>
1	Front signal <i>one</i>	\$ 150.00 <i>✓</i>
1	Side mirror (1 set) <i>11</i>	\$ 120.00 <i>X</i>
1	Handle-bar <i>11</i>	\$ 135.00 <i>X</i>
1	Handle-bar balancer (1 set) <i>11</i>	\$ 80.00 <i>X</i>
1	Hand grip (1 set) <i>11</i>	\$ 60.00 <i>X</i>
2	Brake lever <i>n/s cur 0/500 38</i>	\$ 104.00 <i>1pc</i>
1	Front side cowling - malt <i>one 105</i>	\$ 150.00 <i>✓</i>
1	Front side inner cowling <i>one 148</i>	\$ 180.00 <i>✓</i>
1	Footstep panel <i>one 155</i>	\$ 255.00 <i>✓</i>
1	Footstep panel lower cover <i>one 125</i>	\$ 170.00 <i>✓</i>
1	Side stand <i>11</i>	\$ 108.00 <i>X</i>
1	Main stand <i>one</i>	\$ 165.00 <i>✓</i>
1	Fairing cover (1 set) <i>one</i>	\$ 1,350.00 <i>✓</i>
1	Belt cover <i>one</i>	\$ 175.00 <i>✓</i>
1	Air filter cover <i>11</i>	\$ 125.00 <i>X</i>
		\$ 5,877.00
	Less 10%	\$ 587.70
		\$ 5,289.30

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : **Mohammad Danial Fitri**
: **Bin Mohd Shahril Disilva**
(86080176)

Accident Date : **15-Oct-21**

Vehicle No : **FBP8806G**

Yamaha Aerox
Vehicle Model : **GDR155 CVT**
ABS

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>1 set</i>	\$	38.00	<i>10</i>
2	Fork oils <i>11</i>	\$	30.00	<i>X</i>
2	Fork oil seals <i>11</i>	\$	56.00	<i>X</i>
1	Steering cone (1 set) <i>11</i>	\$	120.00	<i>X</i>
1	Rear box <i>11</i>	\$	380.00	<i>250</i>
1	Rear box bracket <i>11</i>	\$	180.00	<i>X</i>
1	Sticker (1 set) <i>11</i>	\$	120.00	<i>60</i>
1	"AEROX" embleen <i>11</i>	\$	60.00	<i>1</i>
		\$	984.00	

S/No. Labour

1	To provide towing (LOD)	\$	60.00	<i>✓</i>
2	To provide wiring and reset headlamp focusing	\$	<i>11</i> 80.00	<i>X</i>
3	To provide labour	\$	450.00	<i>250</i>
		\$	590.00	

Grand Total

\$ 6,863.30

Singapore Dollars: Six Thousand Eight Hundred Sixty-Three and Cents: Thirty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: