

Not Notified
Li Rep B3400L
Resurvey After Repair
4 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKS 4185 T
 MAKE : AUDI
 MODEL : A3 SEDAN 1.4 TFSI AMBIENTE MY 15
 YEAR : 2014
 CHASSIS NO : WAUZZZ8V6F1075190

SURVEYOR NAME : *Kenneth LKK*
 DATE OF SURVEY : *25.10.2021*
 TIME OF SURVEY :

DATE : 19-Oct-21
 DATE OF ACCIDENT : 5-Oct-21
 THIRD PARTY REF : SMP 4076 S / AIG

No.	Parts Description / Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper <i>1514.30</i>			<i>B</i> \$1,514.50	✓
1 pc	front bumper retainer			<i>B</i> \$27.00	✓
1 pc	front bumper reinforcement			<i>R</i> \$522.65	X
1 pc	front bumper fog lamp cover			<i>M</i> \$79.55	✓
1 pc	front bumper spray nozzle cover			<i>R</i> \$41.10	X
1 pc	o/s headlamp <i>1559.85</i>			<i>Cut</i> \$1,559.85	✓
1 pc	head light bulb			<i>R</i> \$500.45	X
1 pc	o/s headlamp spray nozzle			<i>R</i> \$158.65	X
1 pc	o/s front fender			<i>R</i> \$632.75	✓
				\$5,036.50	
	less 10%			\$503.65	
				\$4,532.85	
	To putty and spray paint.			\$600.00	<i>44d</i>
	To check front wiring & focus headlights.			\$30.00	<i>20L</i>
	Labour charges.			\$480.00	<i>400L</i>
TG-ML/-	TOTAL				\$5,642.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg