



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0843/2021/JT
DATE : 13-Oct-21
WIP : 48872

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TAN JIAYING
ADDRESS : BLK 394 JURONG WEST CENTRAL 1
#08-05
SINGAPORE 640694
TELEPHONE : HP +65 93668885
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070103377
VEHICLE NO : **SMT 9488 H**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI S
MODEL YEAR : 24/7/2020
ENGINE NO : CVK 087158
CHASSIS NO : WAUZZZF4.KA111633
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Oct-21
PLACE OF ACCIDENT : THE TRAFFIC JUNCTION OF
THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMT 9488 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X
3	TO RENEW AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHTS. TO REPAIR BONNET. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,850.00	500
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,622.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 9488 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>ok</i>	1	\$	1,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	587.00	x
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$	142.00	✓
4	FRONT BUMPER CENTER GRILLE <i>new</i>	1	\$	196.00	x
5	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$	210.00	x
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$	126.00	✓
7	FRONT RADIATOR GRILLE <i>ok</i>	1	\$	1,332.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$	270.00	x
9	FRONT BUMPER FOAM FILLER PIECE ?	1	\$	124.00	✓
10	FRONT BUMPER REINFORCMENT BAR ?	1	\$	845.00	✓
11	FRONT BUMPER TOP COVER <i>new</i>	1	\$	127.00	✓
12	CAUTION STICKER <i>new</i>	1	\$	14.00	+
13	AIR-CONDITIONER STICKER <i>new</i>	1	\$	8.00	+
14	FRONT BUMPER REINFORCMENT BRACKET <i>new</i>	1	\$	137.00	+
15	FRONT BUMPER REINFORCMENT SUPPORT - LH / RH <i>new</i>	2	\$	58.00	+
16	FRONT PARKING AID SENSOR <i>new</i>	2		TBC	x
17	FRONT PARKING AID SENSOR SEAL <i>new</i>	4	\$	9.00	+
18	HORN - LH / RH <i>new</i>	2	\$	252.00	+
19	HORN BRACKET - LH / RH <i>new</i>	2	\$	58.00	+
20	FRONT HEADLIGHT - LH / RH <i>new</i>	2	\$	15,386.00	x
SUB TOTAL SPARE PARTS			:	\$ 21,668.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 9488 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 420.00	X
22	FRONT CORRUGATED PIPE	1	\$ 93.00	X
23	LOCK CARRIER SUPPORT PANEL	1	\$ 1,016.00	X
24	FRONT COOLANT SUPPORT	2	\$ 76.00	X
25	TEMPERATURE SENSOR BRACKET	1	\$ 19.00	X
26	INTERCOOLER	1	\$ 587.00	X
27	COOLANT	6	\$ 266.00	X
28	FRONT RADIATOR AIR GUIDE - OUTER LH / RH	2	\$ 56.00	X
29	FRONT RADIATOR AIR GUIDE - INNER LH / RH	2	\$ 24.00	X
30	FRONT RADIATOR AIR GUIDE - UPPER	1	\$ 16.00	X
31	FRONT NO PLATE	S/N	\$ 60.00	X
32	SUNDRIES		\$ 300.00	X
TOTAL SPARE PARTS		:	\$ 24,601.00	
TOTAL LABOUR CHARGES		:	\$ 8,622.00	
GRAND TOTAL		:	\$ 33,223.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lj
: 19/10/21
:
:
:
:
: Not Authorised, 04 Days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT