

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron.

CST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0843/2021/JT
9-Nov-21
TONY
1 of 1
SMT 9488 H
AUDI A4 SEDAN 2.0 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT WHEEL SPOILER - LH <i>torn</i>	\$ 73.00	✓ 58.40
GRAND TOTAL		\$ 73.00	

For Premium Automobiles Pte Ltd

Adrian Ling -
09/11/21
A.L.S.



Authorized Signature


Car in

9/11/21

wip 48872

PREMIUM AUTOMOBILES

Botak/



55 UBI ROAD 1, SINGAPORE 408593

TEL : 6366 2323 FAX : 6841 1163

EMAIL : NORA.KHAZ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 9488 H

 STG - Adnan
 - 4 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>at d</i>	1	\$ 1,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>at n</i>	1	\$ 587.00	+
3	FRONT BUMPER SECURING STRIP <i>at n</i>	2	\$ 142.00	+
4	FRONT BUMPER CENTER GRILLE <i>cracked</i>	1	\$ 196.00	✓
5	FRONT BUMPER CLOSING ELEMENT <i>cracked</i>	1	\$ 210.00	✓
6	FRONT BUMPER AIR GUIDE - LH / RH <i>at n</i>	2	\$ 126.00	+
7	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 1,332.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>at n</i>	2	\$ 270.00	+
9	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 124.00	✓
10	FRONT BUMPER REINFORCEMENT BAR	1	\$ 845.00	?
11	FRONT BUMPER TOP COVER <i>at n</i>	1	\$ 127.00	+
12	CAUTION STICKER <i>3 at n</i>	1	\$ 14.00	+
13	AIR-CONDITIONER STICKER	1	\$ 8.00	+
14	FRONT BUMPER REINFORCEMENT BRACKET <i>at n</i>	1	\$ 137.00	+
15	FRONT BUMPER REINFORCEMENT SUPPORT - LH / RH <i>at n</i>	2	\$ 58.00	+
16	FRONT PARKING AID SENSOR <i>3 at n</i>	2	TBC	+
17	FRONT PARKING AID SENSOR SEAL	4	\$ 9.00	+
18	HORN - LH / RH <i>3 at n</i>	2	\$ 252.00	+
19	HORN BRACKET - LH / RH	2	\$ 58.00	+
20	FRONT HEADLIGHT - LH / RH <i>at n</i>	2	\$ 15,386.00	+

SUB TOTAL SPARE PARTS

: \$ 21,668.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NGRA.PHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 9488 H

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 420.00	X	
22	FRONT CORRUGATED PIPE	1	\$ 93.00	X	
23	LOCK CARRIER SUPPORT PANEL	1	\$ 1,016.00	✓	
24	FRONT COOLANT SUPPORT	2	\$ 76.00	✓	
25	TEMPERATURE SENSOR BRACKET	1	\$ 18.00	✓	
26	INTERCOOLER	1	\$ 587.00	✓	
27	COOLANT	6	\$ 265.00	✓	
28	FRONT RADIATOR AIR GUIDE - OUTER LH / RH	2	\$ 56.00	X	28. Lit torn
29	FRONT RADIATOR AIR GUIDE - INNER LH / RH	2	\$ 24.00	✓	
30	FRONT RADIATOR AIR GUIDE - UPPER	1	\$ 16.00	✓	
31	FRONT NO PLATE	S/N	\$ 60.00	✓	
32	SUNDRIES		\$ 300.00	✓	
TOTAL SPARE PARTS			\$ 24,601.00		
TOTAL LABOUR CHARGES			\$ 8,622.00		
GRAND TOTAL			\$ 33,223.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

SINGAPORE ACCIDENT STATEMENT