



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7567K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT FENDER RH	DEFORMED	588.80	588.80
1	FRT FENDER EMBLEM RH	NECESSARY	26.60	26.60
1	FRT DOOR ASSY RH	DEFORMED	1,797.20	1,797.20
1	FRT DOOR PROTECTOR RH	NECESSARY	110.00	110.00
1	REAR DOOR ASSY RH	DEFORMED	1,789.90	1,789.90
1	REAR DOOR PROTECTOR LH	NECESSARY	110.00	110.00
1	REAR FENDER RH	DEFORMED	1,768.30	1,768.30
1	GARNISH ASSY-DELTA RH	MISSING	42.80	42.80
	LESS 20% DISCOUNT		-1,246.72	-1,246.72
			4,986.88	4,986.88
<u>NETT ITEMS</u>				
1	FRT DOOR COMFORT LOGO (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LOGO (N)	NECESSARY	80.00	80.00
	LESS 10% DISCOUNT		-	-15.50
			155.00	139.50
<u>LABOUR</u>				
	PANEL BEATING.		1,200.00	1,050.00
	SPRAY PAINT.		1,250.00	1,250.00
	CHECK WIRING.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX UPHOLSTERY REAR.		120.00	40.00
	TRANSFER DOOR PARTS.		200.00	100.00
			2,870.00	2,480.00
GRAND TOTAL			8,011.88	7,606.38

Report Ref No. NS/INC21010770/Vqcn2

RECOMMENDED COST OF REPAIRS (CONFIRMED)			7,606.38
--	--	--	-----------------

Report Ref No. NS/INC21010770/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.