

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Accident Date : 18.10.2021

Not Notified  
L1 by @  
Paying After Policy  
2 days  
Third Party

Policy No: \_\_\_\_\_

Date: 19.10.2021

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	<b>Estimate Cost of Repair to "Toyota Altis" Reg. No. SMD6064B Claiming Against Your Insured Veh. No. SGZ7720P</b>		
1pc	Front Bumper	3.80	Bur 565.00 ✓
12pcs	Front Bumper Clips		na 45.60 ✓
1pc	Front Bumper Bracket RH		n 82.60 x
1pc	Front Bumper Sponge		n 115.90 x
1pc	Front Bumper Reinforcement		n 435.00 x
1pc	Front Bumper Fog Lamp RH		n 110.00 x
1pc	Front Bumper Fog Lamp Cover RH		cut 203.00 x
1pc	Front Bumper Center Air Grille		na 169.95 ✓
1pc	Front Bumper Corner Retainer RH		Dis 286.40 ✓
1pc	Grille		na 715.90 ✓
1pc	Grille Emblem		na 95.00 ✓
1pc	Headlamp RH		cut 2,488.95 ✓
	Less 25%		5,313.30
	Front Number Plate		1,328.33
	To Conduct Electrical Check, Focus Headlamp		3,984.98
	Labour Charge - Panel Beating, Repairing Of Front Headlamp Panel, Support & Part Replacement		na 45.00 SN ✓
	To Spray Painting Affected Areas		30.00 2ok
			400.00 22cl
			380.00 22cl
	<b>Total :</b>		<b>4,839.98</b>

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: