

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP ching.

Xiao Chen.

19 October 2021

QUOTATION FOR ACCIDENT REPAIR OF SLZ9167P SUBARU IMPREZA

THIRD PARTY INSURER: CHINA TAIPING

JF16K7KL SJ6009219.

S/No.	Parts	Qty	Amount(\$)
1.	Rear boot lid <i>Reps</i>	1	\$ 1092.00 +
2.	Rear boot lid "Logo" emblem	1	\$ 85.00 ✓
3.	Rear boot lid "Subaru" emblem	1	\$ 80.00 ✓
4.	Rear boot lid "Symmetrical" emblem <i>noc</i>	1	\$ 55.00 ✓
5.	Rear boot lid "AWD" emblem	1	\$ 62.00 ✓
6.	Rear boot lid "Impreza" emblem <i>3x</i>	1	\$ 78.00 ✓
7.	Rear boot lid "Eyesight" emblem	1	\$ 53.00 ✓
8.	Rear boot lid weather strip <i>3x</i>	1	\$ 246.00 +
9.	Rear boot lid mechanism lock	1	\$ 230.00 +
10.	Rear boot lid lock striker <i>3x</i>	1	\$ 55.00 +
11.	Rear boot lid keyless smart	1	\$ 167.00 +
12.	Rear bumper <i>Dehnd</i>	1	\$ 780.00 <i>456</i>
13.	Rear bumper reverse sensor <i>2 pieces dented</i>	4	218.00 \$ 872.00 <i>436</i>
14.	Rear bumper reverse sensor holder <i>3x</i>	4	56.00 \$ 224.00 <i>80</i>
15.	Rear bumper reinforcement beam <i>Dented</i>	1	\$ 288.00 ✓
16.	Rear bumper side retainer L/R <i>3x</i>	2	98.00 \$ 196.00 +
17.	Rear bumper towing cover <i>Dehnd</i>	1	\$ 43.00 ✓
18.	Rear end panel <i>Dented</i>	1	\$ 520.00 ✓
19.	Rear end panel garnish <i>Dehnd</i>	1	\$ 285.00 ✓
Subtotal before discount			\$ 5411.00
Discount 20%			\$ 1082.20
Subtotal 1			\$ 4328.80

2521
2016.80

S/Nett.	Parts	Qty	Amount(\$)
1.	Rear bumper clip <i>3x</i>	1	\$ 30.00 ✓
2.	Rear end panel garnish clip <i>50</i>	1	\$ 30.00 <i>20</i>
Subtotal 2			\$ 60.00

Labour

To check wirings.

~~\$ 80.00~~ *30*

To remove, refix rear reverse sensor

1350

~~\$ 100.00~~ *60*

To remove and reinstall rear interior trims, garnish, seat, etc for necessary repair

~~\$ 180.00~~ *60*

LKK Auto Consultants hence notify

the Repairer of the following:

To straighten, repair, realign on affected area and replace damaged parts

~~\$ 1000.00~~ *600*

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• To spray painting on affected area

~~\$ 1000.00~~ *600*

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Labour Cost

\$ 2360.00 *6748.80*

Total: 3416.80

A/S: 2.7K

Adnan L
H/S 20/10/21
05 Days

Acknowledged by Repairer

Signature:

Date: