



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

P/P #3547-20 3 days

*Not Authorized
 here
 Take photo before party
 29/10/21*

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN.: MOTOR CLAIMS FAX:		NAME: _____ ADDRESS: _____ TEL: _____		WIP: 10073 EXCESS: _____ DATE: 14-Oct-21	
VEH NO:	SLE2968B	DATE IN:		CONTACT PERSON:	RONALD
CHASSIS NO:	JM6BM42A8G0342341	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA 3	DATE REG.:	15-Jul-16	POLICY NO.:	

NATURE OF WORKS

Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1			MBPD8-50-221ABB	<i>DD/DC</i>	\$ 1,047.30
2	COVER TOWING LH	1			MBHN1-50-EL1 BB	<i>DD</i>	\$ 16.50
3	BRACKET CENTER REAR BUMPER	1			MDFR5-50-251	<i>DD</i>	\$ 5.40
4	REINFORCEMENT REAR	1			MB45A-50-260	<i>DD</i>	\$ 564.20
5	TAPE, PROTECTOR	3			MG51D-50-EM1A	<i>DD</i>	\$ 25.80
6	RETAINER S.S ULTRASONIC CENTER	2			MKD47-67-UC5A13	<i>DD</i>	\$ 36.40
7	SENSOR, ULTRASONIC CENTER	2			MKD47-67-UC1 64	<i>DD</i>	\$ 407.20
8	RIVET	4			MBBM4-50-355	<i>DD</i>	\$ 18.00
9	CLIP	2			MGJ21-50-049	<i>DD</i>	\$ 6.80
10	FASTENER	4			MB45A-56-146A	<i>DD</i>	\$ 12.00
11	GROMMET, SCREW	4			MBHN1-50-0Z1A	<i>DD</i>	\$ 10.80
12	REFLECTOR LH	1			MD350-51-5L0E	<i>DD</i>	\$ 53.00
13	GASKET TAIL LAMP RH	1			MBHN1-51-153	<i>DD</i>	\$ 22.00
14	GASKET TAIL LAMP LH	1			MBHN1-51-163	<i>DD</i>	\$ 22.00
					TOTAL PARTS		\$ 2,247.40
					TOTAL PARTS COST		\$ 2,247.40

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	LKK Auto Consultants hence notify the Repairer of the following:						
2	• To resurvey before/after spray painting						
3	• To display damaged part(s) during resurvey						
	• Parts prices are subject to confirmation						
	• Third party survey is on a "Without Prejudice" basis						
	• No illegal modification(s) is allowed						
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company						
					TOTAL PARTS		\$ -
					TOTAL PARTS COST		\$ -
Acknowledged by Repairer							
Signature: _____							

Labour Description

			REVISED	PRICES
1		TO REPLACE REAR BUMPER.	660	\$ 1,320.00
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,260.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	180	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 300.00
6	MZ-BR-SUNDRI	SUNDRIES.	net 20	\$ 50.00
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ 3,840.00
			TOTAL PARTS	\$ - \$ 2,247.40
			TOTAL	\$ - \$ 6,087.40
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ 6,087.40
			GST 7%	\$ - \$ 426.12
			GRAND TOTAL	\$ - \$ 6,513.52
SUPPLEMENTARY LABOUR DESCRIPTION				
			REVISED	PRICES
1		#N/A		
2		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

 Authorised Signature



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION



EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN : MOTOR CLAIMS FAX :		NAME : ADDRESS : TEL :		WIP : 10073 EXCESS : DATE: 14-Oct-21			
VEH NO :	SLE2968B	DATE IN :		CONTACT PERSON :	RONALD		
CHASSIS NO :	JM68M42A8G0342341	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	MAZDA 3	DATE REG.:	15-Jul-16	POLICY NO. :			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1			MBPD8-50-221ABB	\$ 1,047.30	\$ 1,047.30
2	COVER TOWING LH	1			MBHN1-50-EL1 BB	\$ 16.50	\$ 16.50
3	BRACKET CENTER REAR BUMPER	1			MDFR5-50-251	\$ 5.40	\$ 5.40
4	REINFORCEMENT REAR	1			MB45A-50-260	\$ 564.20	\$ 564.20
5	TAPE,PROTECTOR	3			MGS1D-50-EM1A	\$ 25.80	\$ 25.80
6	RETAINER S.S ULTRASONIC CENTER	2			MKD47-67-UC5A13	\$ 36.40	\$ 36.40
7	SENSOR,ULTRASONIC CENTER	2			MKD47-67-UC1 64		\$ 407.20
8	RIVET	4			MB8M4-50-355	\$ 18.00	\$ 18.00
9	CLIP	2			MGJ21-50-049	\$ 6.80	\$ 6.80
10	FASTENER	4			MB45A-56-146A	\$ 12.00	\$ 12.00
11	GROMMET,SCREW	4			MBHN1-50-0Z1A	\$ 10.80	\$ 10.80
12	REFLECTOR LH	1			MD350-51-5L0E		\$ 53.00
13	GASKET TAIL LAMP RH	1			MBHN1-51-153	\$ 22.00	\$ 22.00
14	GASKET TAIL LAMP LH	1			MBHN1-51-163	\$ 22.00	\$ 22.00
					TOTAL PARTS	\$ 1,787.20	\$ 2,247.40
					TOTAL PARTS COST	\$ 1,787.20	\$ 2,247.40
SUPPLEMENTARY							
NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1							
2							
3							
					TOTAL PARTS		\$ -
					TOTAL PARTS COST		\$ -
Labour Description							

			REVISED	PRICES	
1		TO REPLACE REAR BUMPER	\$ 660.00	\$ 1,320.00	
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	\$ 630.00	\$ 1,260.00	
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS	\$ 180.00	\$ 660.00	
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	\$ 120.00	\$ 250.00	
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	\$ 150.00	\$ 300.00	
6	MZ-BR-SUNDRI	SUNDRIES	\$ 20.00	\$ 50.00	
<u>REMARKS:</u> 3 Repair Days			TOTAL LABOUR	\$ 1,760.00	\$ 3,840.00
			TOTAL PARTS	\$ 1,787.20	\$ 2,247.40
			TOTAL	\$ 3,547.20	\$ 6,087.40
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 3,547.20	\$ 6,087.40
			GST 7%	\$ 248.30	\$ 426.12
			GRAND TOTAL	\$ 3,795.50	\$ 6,513.52
<u>SUPPLEMENTARY LABOUR DESCRIPTION</u>					
			REVISED	PRICES	
1		#N/A			
2		#N/A			
<u>REMARKS:</u>			TOTAL LABOUR		
			TOTAL PARTS		
			TOTAL		
			LESS EXCESS		
			TOTAL AFTER EXCESS		
			GST 7%		
			GRAND TOTAL		

TRANS EUROKARS PTE LTD

Authorised Signature