

ASSIGNMENT

From: Date:

Estimated Cost:

OD GP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

850K.

Consistent? : Yes or No

Consistent? : Yes or No

3 days Res.: Yes or No

1.3% 3 Val.: Yes or No

199h

Vehicle: IN / OUT

27A 35640

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Bm / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

SLC2968B

15/7/16

CA/

mazda 3

Grey

82718

JM6BM 42A860342341

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Nil / S/Bm / STD A/Rim or

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Dep 9/6.

29/11/12 confirmed P/P 3547-20 with Ben

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$))

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

S + RS. SI

Photos

Others

TOTAL



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS SERVICES

EQ INSURANCE COMPANY LTD		NAME :		WIP : 10073	
5 Maxwell Road		ADDRESS :		EXCESS :	
#17-00 Tower Block				DATE : 14-Oct-21	
MND Complex, Singapore 069110					
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SLE2968B	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	JM6BM42A8G0342341	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG.:	15-Jul-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1			MBPD8-50-221ABB	DO/PC	\$ 1,047.30
2	COVER TOWING LH	1			MBHN1-50-EL1 BB	DO	\$ 16.50
3	BRACKET CENTER REAR BUMPER	1			MDFR5-50-251	REI	\$ 5.40
4	REINFORCEMENT REAR	1			MB45A-50-260	DO	\$ 564.20
5	TAPE, PROTECTOR	3			MG51D-50-EM1A	REI	\$ 25.80
6	RETAINER S.S ULTRASONIC CENTER	2			MKD47-67-UC5A13	REI	\$ 36.40
7	SENSOR, ULTRASONIC CENTER	2			MKD47-67-UC1 64	REI	\$ 407.20
8	RIVET	4			MBBM4-50-355	REI	\$ 18.00
9	CLIP	2			MGJ21-50-049	REI	\$ 6.80
10	FASTENER	4			MB45A-56-146A	REI	\$ 12.00
11	GROMMET, SCREW	4			MBHN1-50-021A	REI	\$ 10.80
12	REFLECTOR LH	1			MD350-51-5L0E	REI	\$ 53.00
13	GASKET TAIL LAMP RH	1			MBHN1-51-153	REI	\$ 22.00
14	GASKET TAIL LAMP LH	1			MBHN1-51-163	REI	\$ 22.00
TOTAL PARTS							\$ 2,247.40
TOTAL PARTS COST							\$ 2,247.40

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	LKK Auto Consultants hence notify the Repairer of the following:						
2	• To resurvey before/after spray painting						
3	• To display damaged part(s) during resurvey						
	• Parts prices are subject to confirmation						
	• Third party survey is on a "Without Prejudice" basis						
	• No illegal modification(s) is allowed				TOTAL PARTS		\$ -
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				TOTAL PARTS COST		\$ -
	Acknowledged by Repairer						
	Signature:				Labour Description		

			REVISED	PRICES
1		TO REPLACE REAR BUMPER	660	\$ 1,320.00
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	630	\$ 1,260.00
3	MZ-BR-REVS	TO TRANSFER REVERSE SENSORS	180	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	150	\$ 300.00
6	MZ-BR-SUNDRI	SUNDRIES	net 20	\$ 50.00
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ 3,840.00
			TOTAL PARTS	\$ - \$ 2,247.40
			TOTAL	\$ - \$ 6,087.40
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ 6,087.40
			GST 7%	\$ - \$ 426.12
			GRAND TOTAL	\$ - \$ 6,513.52
SUPPLEMENTARY LABOUR DESCRIPTION				
			REVISED	PRICES
1		#N/A		
2		#N/A		
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ - \$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

 Authorised Signature



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZATION

EUROKARS SERVICES

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : ADDRESS : TEL :		WIP : 10073 EXCESS : DATE : 14-Oct-21	
VEH NO :	SLE2968B	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	JM6BM42A8G0342341	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG. :	15-Jul-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1			MBPD8-50-221ABB	\$ 1,047.30	\$ 1,047.30
2	COVER TOWING LH	1			MBHN1-50-EL1 BB	\$ 16.50	\$ 16.50
3	BRACKET CENTER REAR BUMPER	1			MDFR5-50-251	\$ 5.40	\$ 5.40
4	REINFORCEMENT REAR	1			MB45A-50-260	\$ 564.20	\$ 564.20
5	TAPE, PROTECTOR	3			MGS1D-50-EM1A	\$ 25.80	\$ 25.80
6	RETAINER S.S ULTRASONIC CENTER	2			MKD47-67-UC5A13	\$ 36.40	\$ 36.40
7	SENSOR, ULTRASONIC CENTER	2			MKD47-67-UC1 64		\$ 407.20
8	RIVET	4			MBBM4-50-355	\$ 18.00	\$ 18.00
9	CLIP	2			MGJ21-50-049	\$ 6.80	\$ 6.80
10	FASTENER	4			MB45A-56-146A	\$ 12.00	\$ 12.00
11	GROMMET, SCREW	4			MBHN1-50-021A	\$ 10.80	\$ 10.80
12	REFLECTOR LH	1			MD350-51-5L0E		\$ 53.00
13	GASKET TAIL LAMP RH	1			MBHN1-51-153	\$ 22.00	\$ 22.00
14	GASKET TAIL LAMP LH	1			MBHN1-51-163	\$ 22.00	\$ 22.00
						TOTAL PARTS	\$ 1,787.20
						TOTAL PARTS COST	\$ 1,787.20

SUPPLEMENTARY

NO	DESCRIPTION	QTY	1st	Supp	PARTS NO	REVISED	PRICES
1							
2							
3							
						TOTAL PARTS	\$ -
						TOTAL PARTS COST	\$ -

Labour Description

			REVISED	PRICES
1		TO REPLACE REAR BUMPER	\$ 660.00	\$ 1,320.00
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	\$ 630.00	\$ 1,260.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS	\$ 180.00	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	\$ 120.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	\$ 150.00	\$ 300.00
6	MZ-BR-SUNDRI	SUNDRIES	\$ 20.00	\$ 50.00
REMARKS: 3 Repair Days		TOTAL LABOUR	\$ 1,760.00	\$ 3,840.00
		TOTAL PARTS	\$ 1,787.20	\$ 2,247.40
		TOTAL	\$ 3,547.20	\$ 6,087.40
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ 3,547.20	\$ 6,087.40
		GST 7%	\$ 248.30	\$ 426.12
		GRAND TOTAL	\$ 3,795.50	\$ 6,513.52
SUPPLEMENTARY LABOUR DESCRIPTION				
			REVISED	PRICES
1		#N/A		
2		#N/A		
REMARKS:		TOTAL LABOUR		
		TOTAL PARTS		
		TOTAL		
		LESS EXCESS		
		TOTAL AFTER EXCESS		
		GST 7%		
		GRAND TOTAL		

TRANS EUROKARS PTE LTD

Authorised Signature