

## TRANS EUROKARS PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042

## **ESTIMATE COST OF REPAIRS**



EQ IN	SURANCE COME	NAME:				WIP:		10073		
5 Max	well Road	ADDRESS :					EXCESS:			
‡17-00 Tower Block								DATE:	1	4-Oct-21
MND Complex, Singapore 069110										
ATTN.: MOTOR CLAIMS			TEL:							
FAX:										
VEH N	0:	SLE2968B	DATE IN :				CONTACT PERSON :	RONALD		
CHASS	IS NO :	JM6BM42A8G0342341	MILEAGE :	GE:			TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL: MAZDA 3		DATE REG.:	15-Jul-16			POLICY NO. :				
			<u>N</u>	IATURE (	OF WOR	KS_				
	Parts Description									
NO		DESCRIPTION		QTY	1st	Supp	PARTS NO	REVISED		PRICES
1	REAR BUMPER			1			MBPD8-50-221ABB		\$	1,047.30
2	COVER TOWING	LH		1			MBHN1-50-EL1 BB		\$	16.50
3	BRACKET CENTER REAR BUMPER			1			MDFR5-50-251		\$	5.40
4	REINFORCEMENT REAR			1			MB45A-50-260		\$	564.20
5	TAPE,PROTECTO	R		3			MGS1D-50-EM1A		\$	25.80
6	RETAINER S.S ULTRASONIC CENTER			2			MKD47-67-UC5A13		\$	36.40
7	SENSOR,ULTRAS	ONIC CENTER		2			MKD47-67-UC1 64		\$	407.20
8	RIVET			4			MBBM4-50-355		\$	18.00
9	CLIP			2			MGJ21-50-049		\$	6.80
10	FASTENER			4			MB45A-56-146A		\$	12.00
11	GROMMET,SCRE	EW		4			MBHN1-50-0Z1A		\$	10.80
12	REFLECTOR LH			1			MD350-51-5L0E		\$	53.00
13	GASKET TAIL LAN	MP RH		1			MBHN1-51-153		\$	22.00
14	GASKET TAIL LAMP LH			1			MBHN1-51-163		\$	22.00
							TOTAL PARTS		\$	2,247.40
							TOTAL PARTS COST		\$	2,247.40
	<u>SUPPLEMENTARY</u>									
NO	DESCRIPTION			QTY	1st	Supp	PARTS NO	REVISED		PRICES
1										
2										
3										
							<del>,</del>			
							TOTAL PARTS		\$	-
							TOTAL PARTS COST		\$	-
<u>Labour Description</u>										

				REV	VISED		PRICES
1		TO REPLACE REAR BUMPER.				\$	1,320.00
2		TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.				\$	1,260.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.					660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$	250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$	300.00
6	MZ-BR-SUNDRI	SUNDRIES.				\$	50.00
	REMARKS:		TOTAL LABOUR	\$	-	\$	3,840.00
	THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND				-	\$	2,247.40
	SHOULD THERE	BE MORE DAMAGES FOUND DURING THE PROCESS	TOTAL	\$	-	\$	6,087.40
	•	OU WILL BE INFORMED BEFORE THE REPAIRS ARE	LESS EXCESS	\$	_	\$	-
		OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TH THE REPAIRS, A <b>QUOTATION FEE OF \$400</b>	TOTAL AFTER EXCESS	\$	-	\$	6,087.40
		ACCORDINGLY FOR MAN-HOURS INVOLVED IN	GST 7%	\$	-	\$	426.12
	SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.		GRAND TOTAL	\$	-	\$	6,513.52
		SUPPLEMENTARY LABOUR DESCRIPTION	•			•	
				REV	VISED		PRICES
1		#N/A					
2		#N/A					
	REMARKS:	1	TOTAL LABOUR	\$	_	\$	_
	THIS IS ONLY AN	ESTIMATE FROM VISUAL INSPECTION AND	TOTAL PARTS	\$	-	\$	-
	SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS		TOTAL	\$	-	\$	-
	•	OU WILL BE INFORMED BEFORE THE REPAIRS ARE OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT	LESS EXCESS	\$	-	\$	-
		TOTAL AFTER EXCESS	\$	-	Ė		
	TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400  WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN  SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.  GRAND TOTAL  GRAND TOTAL				-	\$	-
					_	\$	_

## TRANS EUROKARS PTE LTD

Authorised Signature	