

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Oct-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1054 Y

1 pc	Bootlid CRDi <i>X</i>	<i>Resul</i>	\$	29.00
1 pc	Boot lid lower garnish <i>X</i>	<i>Hp 90010068</i>	\$	290.00
1 pc	Rear bumper <i>de</i>		\$	696.00
1 pc	Rear bumper lower cover <i>sca</i>	<i>2 days</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	<i>4/8</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>?</i>	<i>25/10/21</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>?</i>	<i>@ 1510</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X</i>		\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>?</i>	<i>Resy after</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>?</i>	<i>repair</i>	\$	36.00
			\$	<u>2,180.00</u>
		Less 10%	\$	218.00
			\$	<u>1,962.00</u>

S/NETT

1 set	Rear bumper clips <i>na</i>		\$	48.00 <i>30</i>
1 set	Bootlid lower garnish clips <i>X</i>		\$	60.00 <i>X</i>
1 set	Bootlid stickers <i>X</i>		\$	100.00 <i>X</i>
1 set	Reverse sensor <i>sca</i>		\$	280.00 <i>200</i>
	Sundry		\$	50.00 <i>X</i>
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	60.00 <i>40</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc		\$	650.00 <i>200</i>
	To putty and spray painting on bootlid lower garnish, rear bumper, end panel		\$	600.00 <i>200</i>
	To apply rustproofing on the repaired and replaced panels.		\$	<u>100.00</u> <i>X</i>
			\$	<u>4,090.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.