

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Oct-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1054 Y

1 pc	Bootlid CRDi XM	Resul	\$	29.00
1 pc	Boot lid lower garnish XM	Hp 90010068	\$	290.00
1 pc	Rear bumper de/	2 days	\$	696.00 ✓
1 pc	Rear bumper lower cover sca/	4s	\$	206.00 ✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 XM	25/10/21	\$	58.00
1 pc	Rear bumper inner sponge ? XM	@ 1510	\$	114.00
1 pc	Rear bumper reinforcement ? XM	XM Resy after	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 XM	repair	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 XM		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 XM		\$	36.00
			\$	2,180.00
			Less 10%	\$ 218.00
			\$	1,962.00

902
10%
811.80

S/NETT

1 set	Rear bumper clips n/		\$	48.00 30
1 set	Bootlid lower garnish clips XM		\$	60.00 XM } 230
1 set	Bootlid stickers X n/		\$	100.00 XM
1 set	Reverse sensor sca/		\$	280.00 200
Sundry			\$	50.00 X 11
	To dismantle / replace reverse sensor to new bumper and reset to the same	811.80	\$	60.00 40
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	230.00	\$	180.00 XM 440
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	440.00	\$	650.00 200
	To putty and spray painting on bootlid lower garnish, rear bumper, end panel	1481.80	\$	600.00 200
	To apply rustproofing on the repaired and replaced panels.	20%	\$	100.00 XM
		1185.44	\$	
		4s-1,150	\$	
			\$	4,090.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.