

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 20 October 2021

To : LKK

Attn : Bryan

Tel: 97237799

Taufik

VEHICLE NO : FBG 1097D

Yamaha FZ16

ACCIDENT DATE: 17 October 2021

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Rear Mudguard	1	135.00 X ny
2 Rear RH Signal	1	65.00 X ny
3 Tail Lamp	1	130.00 X ny
4 Rear Centre Panel	1	150.00 X ny
5 Handle Bar	1	95.00 X ny
6 Brake Lever	1	65.00 cut
7 Exhaust Guard	1	180.00 X ny
8 Rear LH Tail Side Panel	1	120.00 cut
9 Gear Pedal	1	80.00 bt
10 Gear Rod	1	75.00 X ny
11 Mirror - Universal	1 set	180.00 bno
12 LH Tank Cover	1	250.00 cut
13 Engine Cover	1	195.00 X ny
Sub-Total		1,720.00
Less 10%		172.00
Sub-Total		1,548.00

695  
10% 625.50

VEHICLE NO : FBG 1097D

Yamaha FZ16

Nett items

- 1 Towing fee
- 2 Remove & replace above parts, align & etc
- 3 Putty & touch up paint work
- 4 Fork Reprers

40.00 800  
250.00 150

200.00 150

180 120

Sub-Total

490.00

Nett Total

2,038.00 420.

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

Tanfuin 97495749

WP' 20/00/2105pm

4/5 Resurvey after repair

tanfuin@lkkauto.com.

3 days

625.50

420

1045.50

4/5 800 3 days #

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: