

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 20 October 2021

To : LKK

Attn : ~~Bryan~~

Tel: 97237799

Taufik

VEHICLE NO : FBG 1097D

Yamaha FZ16

ACCIDENT DATE: 17 October 2021

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Rear Mudguard	1	135.00 X
2 Rear RH Signal	1	65.00 x
3 Tail Lamp	1	130.00 X
4 Rear Centre Panel	1	150.00 x
5 Handle Bar	1	95.00 ?
6 Brake Lever	1	65.00 cut ✓
7 Exhaust Guard	1	180.00 x
8 Rear LH Tail Side Panel	1	120.00 cut ✓
9 Gear Pedal	1	80.00 bit ✓
10 Gear Rod	1	75.00 in ✓
11 Mirror - Universal	1 set	180.00 kno ✓
12 LH Tank Cover	1	250.00 cut ✓
13 Engine Cover	1	195.00 x
Sub-Total		1,720.00
Less 10%		172.00
Sub-Total		1,548.00

865
778.50

VEHICLE NO : FBG 1097D

Yamaha FZ16

Nett items

- 1 Towing fee
- 2 Remove & replace above parts, align & etc
- 3 Putty & touch up paint work

40.00 ?
250.00 150
200.00 150

Sub-Total

490.00

Nett Total

2,038.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

Tanfiah 97495749
WP 20/00/21 E 5pm
L/S Resurvey after repair
tanfiah@lkkauto.com
3 days

228.50
340
1118.50
2158.9004
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: