

ASS. REP. BY:

Steve

CS/KT 21010.793/E43

ASSIGNMENT

From:

Date:

Estimated Cost:

OP/TP/WS/TP/RR/OD/RES/EVA/INV/MV

To inspect Vehicle Not

at Workshop m/s

Insured:

Policy No.

Claims No.


Sum Insured:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Rel. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Sent

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Sum Sent

%

3 Vol.: Yes or No

GA / REV / REP. / 24 HRS

Vehicle: IN/OUT

Date:

Person Contacted:

Veh No:

SLR 8144D

Yr Regn:

29/8/17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

March 3

CB

1496

Colour:

Blue

A/C:

Insured / Std / NI / N

Sp. Reading

49876

T/Radio:

Insured / Std / NI / N

Eng/No:

JM 68X12278H0162614

C/No:

Gen. Cond: Good / Fair / Poor / Buppt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Pi

295/60R16

Ri

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Tayo

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

1/11/21

D.O.A.

21/10/21

Survey held at

LIM CITY

Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Roof/ or

The U/C / CHASSIS frame / Body Structure affected due to collision

Date / Time

Action / Instruction

INV-57K

Mar/Tue, File, Retain



Procl. Report



Final Report

Mar/Tue, File, Retain

Days Of Repair:

Resurvey No. of Trips:

Survey Fee:

Transportation:

S + RS, \$

Final

Survey

Vehicle

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Vehicle (\$

Mar/Tue, File, Retain

Mar/Tue, File, Retain

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

lnk AL
L/S
M AL sy
3 days

Steve CLKK)
21/10/21, 10:30am

Ms China Taiping Insurance (Singapore) Pte Ltd
Date 20/10/2021
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLR8144D
Chassis No: JM6BN22A8H0162674
MAKE / MODEL : Mazda 3 Sedan 1.5 AT
DATE OF ACCIDENT: 17/10/2021
YOUR INSURED VEHICLE NUMBER: GBC8716B
MILEAGE: 49874 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Front door LH / ON	1PC	\$ 1,500.00	\$ 1,500.00
2	Front side mirror assembly (LH) / BR	1PC	\$ 980.00	\$ 980.00
				\$ 2,480.00
		20% DISCOUNT S\$:	\$ 496.00	\$ 1,984.00

SPECIAL NETT

1	Front door 'Get-go' sticker / MC	1 SET	\$250.00	150
	Special Nett Total S\$:		\$250.00	

LABOUR CHARGES

1	To labour charge for removing rear door(LH) out to facilitate repairs of damage parts	\$ 500.00	200
2	To respray front door(LH) and side mirror cover(LH)	\$ 500.00	270

LABOUR TOTAL S\$:	\$ 1,000.00
TOTAL S\$:	\$ 2,984.00
7% GST	\$ 208.88
GRAND TOTAL S\$:	\$ 3,192.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: