

Our Job Ref No : 305490439
Date : 21/10/21

ENGINEERING
ComfortDelGro Engineering Pte Ltd
89 Loyang Drive, Singapore 508900
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHA1667U


Fax : _____
13/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- 1. The repair job shall bill to: NTUC FBQ3267P
- 2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$950.00 X
\$850
- 3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :  _____
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature :  _____
Name : Thevan
Date : 22/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: _____

REPAIR ESTIMATE*

VEHICLE NO SHA1667U ✓

MAKE HYUNDAI

MODEL I-40

DATE 13/11/2021 03:15

MVA CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT WING MIRROR ASSY RH			\$670.00
	SUB TOTAL			\$670.00
	20.00% DISCOUNTED TOTAL			\$134.00
				\$536.00
1	FRONT DOOR COMFORT STICKER			\$75.00
	Labour Charge			
	Panel Beating			\$150.00
	Spray Painting (Frt pillar & frt door)			\$400.00
	TOTAL LABOUR			\$550.00
	ESTIMATE TOTAL			\$1,161.00
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

mis

wc

no
500
350

Thevan @lkkhauto.com
82235769

13/10/21 1615

2 days wp

6/5 after repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: