

Our Job Ref No : 305490432  
Date : 15/10/21

**ENGINEERING**  
ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**


To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHB3415L


Fax : \_\_\_\_\_  
Date of Accident : 12/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMG6451B
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \$1,762.86
  - (b) Labour Charges \$1,230.00
  - Total for Part-By-Part Repair Cost** \$2,992.86
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \_\_\_\_\_  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 3 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : THEVAN  
Date : 21/10/21

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305490432  
 REGN NO : SHB3415L  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 28.01.2021  
 DATE/TIME IN : 12.10.2021 13:50  
 ACCIDENT DATE : 12.10.2021

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-2270-G	BOOTLID EMBLEM-HYBRID	1	24.30	20.00	19.44
0002	04-01-0104-2271-G	BOOTLID EMBLEM-IONIQ	1	31.30	20.00	25.04
0003	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0004	04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00
0005	04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00
0006	04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60
0007	04-01-0104-2544-G	REAR BUMPER TOW COVER	1	98.80	20.00	79.04
0008	28-01-0103-0009-A	BOOTLID COMFORTDELGRO	1	35.00	10.00	31.50
0009	28-01-0103-0010-A	BOOTLID 65521111	1	35.00	10.00	31.50
0010	28-01-9999-2026-A	BOOTLID APPS	1	40.00	10.00	36.00
0011	09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00
0012	28-01-0104-2029-A	REAR NO.PLATE W/TRIM CVR	1	55.00	10.00	49.50
0013	04-01-0104-2288-G	REAR BUMPER INFORCEMENT	1	394.80	20.00	315.84

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188


JOB NO : 305490432  
REGN NO : SHB3415L  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 28.01.2021  
DATE/TIME IN : 12.10.2021 13:5  
ACCIDENT DATE : 12.10.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0014 09-01-0104-2133-G REAR SMART KEY ANTENNA	1	40.50	20.00	32.40		
0015 04-01-0104-3919-G REAR BUMPER REIN-BRKT RH	1	138.10	20.00	110.48		
SUB-TOTAL :						1,762.86

## JOB NATURE

0000 PB	PANEL BEATING-SHB3415L	700.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 L	R/I REVERSE SENSOR	30.00
SUB-TOTAL :		1,230.00

TOTAL : 2,992.86

  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 13-Oct-21

LKK-

MODEL: Hyundai IoniqINSURANCE: NTUC (PIP)VEHICLE NO.: SHB3415L - CityCabMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Boot Lid Emblem-Hybrid	1		\$24.30
	Boot Lid Emblem-Ioniq	1		\$31.30
	Rear Bumper	1		\$459.40
	Rear Bumper Reinforcement	1		\$394.80
	Rear Bumper Reinforcement Bracket (LH/RH)	2	\$138.10	\$276.20
	Rear Bumper Reflector (LH/RH)	2	\$41.45	\$82.90
	Rear Bumper Centre Moulding Assy	1		\$451.25
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00
	Rear Bumper Clips	10	\$2.20	\$22.00
	Rear Bumper Fog Lamp	1		\$201.50
	Rear Bumper Towing Cover	1		\$98.80
	Rear Bumper Smart Key Antenna	1		\$40.50
	<b>SUB TOTAL</b>			\$2,237.95
	<b>LESS 20%</b>			\$447.59
	<b>DISCOUNTED TOTAL</b>			\$1,790.36
	Boot Lid ComfortDelGro	1		\$35.00
	Boot Lid 65521111	1		\$35.00
	Boot Lid APPS	1		\$40.00
	Rear Bumper Reverse Sensor	1		\$180.00
	Rear No.Plates W/Trim Cover	1		\$55.00
	<b>S/NETT SUB</b>			\$345.00
	<b>LESS 10%</b>			\$34.50
	<b>S/NETT TOTAL</b>			\$310.50
	<b>SPARE PARTS TOTAL</b>			\$2,100.86
	<b>Labour Charge</b>			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	Remove/Refix Reverse Sensor			\$120.00
	<b>TOTAL LABOUR</b>			\$1,520.00
	<b>ESTIMATE TOTAL</b>			\$3,620.86

LH X svc

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantity will be reported after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuvann@lkkauto.com

82235769

13/10/21 1630

PIP before paint photo

3 clogs w/p

400  
500  
30