



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3415L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOT LID EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	BOOT LID EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	REAR BUMPER	CUT	459.40	459.40
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$138.10	O/S DENTED / N/S SERVICEABLE	276.20	138.10
2	REAR BUMPER REFLECTOR (LH/RH) @\$41.45	SERVICEABLE	82.90	-
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	DISTORTED	155.00	155.00
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.50	-
1	REAR BUMPER TOWING COVER	DISTORTED	98.80	98.80
1	REAR BUMPER SMART KEY ANTENNA	SCRATCHED	40.50	40.50
	LESS 20% DISCOUNT		-447.59	-363.09
			1,790.36	1,452.36
<b><u>NETT ITEMS</u></b>				
1	BOOT LID COMFORTDELGRO (N)	NECESSARY	35.00	35.00
1	BOOT LID 65521111 (N)	NECESSARY	35.00	35.00
1	BOOT LID APPS (N)	NECESSARY	40.00	40.00
1	REAR BUMPER REVERSE SENSOR (N)	CUT	180.00	180.00
1	REAR NO PLATE W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-34.50	-34.50
			310.50	310.50
<b><u>LABOUR</u></b>				
	PANEL BEATING.		800.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,520.00	1,230.00
<b>GRAND TOTAL</b>			<b>3,620.86</b>	<b>2,992.86</b>

Report Ref No. NS/INC21010797/Vucn2

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>2,992.86</b>
--	--	--	-----------------

Report Ref No. NS/INC21010797/Vucn2



**THEVAN THOMAS KARTHIKESAVAN**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.