

Our Job Ref No 305490436

Date 14/10/2021

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

SHD4140L

DOA: 12/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBD9089R
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$850.00
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature :

Name : THEVAN

Date : 21/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

NTUC-CPIP)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.10.2021

Time: 10:31:19

Jumani

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305490436
REGN NO : SHD4140L ✓
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 12.10.2021 16:35
ACCIDENT DATE : 12.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1	459.40	20.00	367.52	Kr
0002 04-01-0104-2533-G IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00	/cut
0003 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/NIC
0004 04-01-0104-2288-G BEAM-RR BUMPER	1	394.80	20.00	315.84	? X SUC
0005 28-01-0104-2029-A VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00	/crq

SUB-TOTAL : 1,106.96

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 780.00

Thuanel Auto Com
82235769

13/10/21 /600

P/P get for paint photo
2 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: