



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**MITSUBISHI**  
**MOTORS**

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM YEW TEE	Cust No/Name	KCV18776/LIM YEW TEE
676B JURONG WEST STREET 64	Reg No/Reg Date	SMX6597A / 25/01/202
#12-241	Date In/Mileage	/ 0
SINGAPORE 642676	Chassis No	GF7W0700983
Contact No	Engine No	4J11CY7036
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV18776	CRDVCH	19/10/2021/ 10:54	TLK	282 / Kevin Leong	16567		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1920.00
REPLACE FRT BUMPER, FRT LH FENDER & AFFECTED AREA							
E PNT98000							1650.00
PAINT WORK ON FRT BUMPER & FRT LH FENDER							
M SUNDRY							100.00
PERFORM RUST PREVENTION							
M SUNDRY							50.00
TO APPLY SEALANT ON AFFECTED AREA							
A 54900099							120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
B WHEELALIGNMENT							192.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							50.00
TO TRANSFER FRT LH RIM INCLUDING BALANCING							
M SUNDRY							600.00
TO SUPPLY FRT LH TYRE							
M SUNDRY							50.00
SUNDRIES							
M	HEADLAMP ASSY,LH			1.00	1948.00	00.00	1948.00
M	LAMP ASSY,FOG,FR LH			1.00	350.00	00.00	350.00
M	FACE,FR BUMPER			1.00	863.00	00.00	863.00
M	BRACKET,FR BUMPER SIDE,LH			1.00	18.00	00.00	18.00
M	GARNISH,FR BUMPER,LH			1.00	48.00	00.00	48.00
M	GARNISH,FR BUMPER SIDE			1.00	112.00	00.00	112.00
M	GARNISH,FR BUMPER SIDE			1.00	220.00	00.00	220.00
M	GARNISH,FR BUMPER SIDE			1.00	48.00	00.00	48.00
M	REINF,FR BUMPER SIDE,LH			1.00	60.00	00.00	60.00
M	REINFORCEMENT,FR BMPR SIDE			1.00	22.00	00.00	22.00
M	FENDER,FR LH			1.00	622.00	00.00	622.00
M	SHIELD,FR WHEELHOUSE,LH			1.00	164.00	00.00	164.00
M	MOULDING,FR BUMPER,LH			1.00	97.00	00.00	97.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LIM YEW TEE	Cust No/Name	KCV18776/LIM YEW TEE
676B JURONG WEST STREET 64	Reg No/Reg Date	SMX6597A / 25/01/202
#12-241	Date In/Mileage	/ 0
SINGAPORE 642676	Chassis No	GF7W0700983
Contact No	Engine No	4J11CY7036
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KCV18776	CRDVCH	19/10/2021/ 10:54	TLK	282 / Kevin Leong	16567		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	MOULDING,FR WHEEL ARCH,LH			1.00	168.00	00.00	168.00
M	WHEEL,DISC			1.00	974.00	00.00	974.00
M	EXTENSION,FR BUMPER			1.00	517.00	00.00	517.00

# Estimate

Confirm &amp; accepted by

	<b>Nett</b>	<b>11,243.00</b>
7% GST on	<b>11243.00</b>	<b>787.01</b>
<b>Total Payable</b>		<b>12,030.01</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.