



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM YEW TEE	Cust No/Name KCV18776/LIM YEW TEE
676B JURONG WEST STREET 64	Reg No/Reg Date SMX6597A / 25/01/202
#12-241	Date In/Mileage / 0
SINGAPORE 642676	Chassis No GF7W0700983
Contact No	Engine No 4J11CY7036
	Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV18776	CRDVCH	19/10/2021/ 10:54	TLK	282 / Kevin Leong	16567			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1250 1920.00
REPLACE FRT BUMPER, FRT LH FENDER & AFFECTED AREA 640 X 2								1190 1650.00
E PNT98000								80 100.00
PAINT WORK ON FRT BUMPER & FRT LH FENDER 550 X 2								X 50.00
M SUNDRY								
PERFORM RUST PREVENTION								
M SUNDRY								
TO APPLY SEALANT ON AFFECTED AREA								120.00
A 54900099								
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								280.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								192.00
B WHEELALIGNMENT								
To Conduct Computerize Full Wheel Alignment								50.00
M SUNDRY								
TO TRANSFER FRT LH RIM INCLUDING BALANCING								600.00
M SUNDRY								
TO SUPPLY FRT LH TYRE								20 50.00
M SUNDRY								
SUNDRIES					1.00	1948.00	00.00	1948.00
M HEADLAMP ASSY, LH					1.00	350.00	00.00	350.00
M LAMP ASSY, FOG, FR LH					1.00	863.00	00.00	863.00
M FACE, FR BUMPER					1.00	18.00	00.00	18.00
M BRACKET, FR BUMPER SIDE, LH					1.00	48.00	00.00	48.00
M GARNISH, FR BUMPER, LH					1.00	112.00	00.00	112.00
M GARNISH, FR BUMPER SIDE					1.00	220.00	00.00	220.00
M GARNISH, FR BUMPER SIDE					1.00	48.00	00.00	48.00
M GARNISH, FR BUMPER SIDE					1.00	60.00	00.00	60.00
M REINF, FR BUMPER SIDE, LH					1.00	22.00	00.00	22.00
M REINFORCEMENT, FR BMRP SIDE					1.00	622.00	00.00	622.00
M FENDER, FR LH					1.00	164.00	00.00	164.00
M SHIELD, FR WHEELHOUSE, LH					1.00	97.00	00.00	97.00
M MOULDING, FR BUMPER, LH								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM YEW TEE  676B JURONG WEST STREET 64 #12-241 SINGAPORE 642676  Contact No	Cust No/Name KCV18776/LIM YEW TEE Reg No/Reg Date SMX6597A / 25/01/202 Date In/Mileage / 0 Chassis No GF7W0700983 Engine No 4J11CY7036 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN ( Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KCV18776	CRDVCH	19/10/2021/ 10:54	TLK	282 / Kevin Leong	16567

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M MOULDING,FR WHEEL ARCH,LH - CUT	1.00	168.00	00.00	168.00
M WHEEL,DISC - CUT	1.00	974.00	00.00	974.00
M EXTENSION,FR BUMPER (Lower Black) - CUT	1.00	517.00	00.00	517.00

Steve (LKK)

28/10/21, 11:00a

WIL P/L

P/P

My Bel Sec

5 days

# Estimate

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	11,243.00
7% GST on	11243.00	787.01
<b>Total Payable</b>		<b>12,030.01</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : STEVE LKK  
Claim : TP INDIA  
DOA : 18.10.2021  
Emailed : 26.11.2021, 5.15pm  
Date survey : 28.10.2021

VEHICLE NO : SMX 6597 A  
MODEL : MIT OUTLANDER 2.0  
WIP : 16567

Material	:	\$	6,309.00
Labour	:	\$	3,297.00
Sub-Total	:	\$	9,606.00
	:		-
Less Excess	:	\$	-
Total	:	\$	9,606.00
GST 7%	:	\$	672.42
Grand Total	:	\$	10,278.42
Finalise By/Date	:		LOI / 26/11/2021

☒ REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 5 WORKING DAYS + 2 Days ( 1 ) Weekends  
+ 0 Days ( 0 ) Public holiday  
TOTAL DAYS REPAIR TOOK = 7

☒ TP claim PC 3719 K

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 28/10/2021	Cust No/Name KCV18776/LIM YEW TEE Reg No/Reg Date SMX6597A / 25/01/2021 Date In/Mileage 28/10/2021/ 6070 Chassis/Package GF7W0700983 /DC17PT Engine No 4J11CY7036 Make/Model MIT/20MY OUTLANDER 2.0 CVT MODERN (997) Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	26/11/2021/ 15:58	TLK	260 / AiTing	16567			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, LH FRONT FENDER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								1280.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								1100.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								120.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								280.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment								192.00
M SUNDRY SUNDRIES								20.00
A 33900099 REPLACE LH FRONT UNDERCARRIAGE PARTS → Supp.								225.00
S SPECIALISTJOB REPLACE LH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								50.00
X	HEADLAMP ASSY,LH				1.00	1948.00	00.00	1948.00
X	FACE,FR BUMPER				1.00	863.00	00.00	863.00
X	BRACKET,FR BUMPER SIDE,LH				1.00	18.00	00.00	18.00
X	GARNISH,FR BUMPER,LH				1.00	48.00	00.00	48.00
X	GARNISH,FR BUMPER SIDE				1.00	112.00	00.00	112.00
X	GARNISH,FR BUMPER SIDE				1.00	220.00	00.00	220.00
X	GARNISH,FR BUMPER SIDE				1.00	48.00	00.00	48.00
X	FENDER,FR LH				1.00	622.00	00.00	622.00
X	SHIELD,FR WHEELHOUSE,LH				1.00	164.00	00.00	164.00
X	MOULDING,FR BUMPER,LH				1.00	97.00	00.00	97.00
X	MOULDING,FR WHEEL ARCH,LH				1.00	168.00	00.00	168.00

This is not an official tax invoice.  
This is a computer generated document, no signature is required.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  28/10/2021	Cust No/Name	KCV18776/LIM YEW TEE
	Reg No/Reg Date	SMX6597A / 25/01/2021
	Date In/Mileage	28/10/2021/ 6070
	Chassis/Package	GF7W0700983 /DC17PT
	Engine No	4J11CY7036
	Make/Model	MIT/20MY OUTLANDER 2.0 CVT MODERN (997)
	Colour/Trim	WO1 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	26/11/2021/ 15:58	TLK	260 / AiTing	16567		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	WHEEL,DISC			1.00	✓ 974.00	00.00	974.00
X	EXTENSION,FR BUMPER			1.00	✓ 517.00	00.00	517.00
X	RIVET,FR BUMPER			10.00	5.00	00.00	50.00
X	CLIP,INST PANEL CONSOLE			10.00	3.00	00.00	30.00
X	CLIP,ENG ROOM COVER			10.00	2.00	00.00	20.00
X	STRUT,FR SUSP,LH			1.00	410.00	00.00	410.00
Z	TEXT						
	TP CLAIM INDIA PC3719K						
	DOA : 18.10.21						
	SURVEYOR STEVE-LKK	28.10.2021					
	REPAIR 05 DAYS						

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	6,309.00	Nett	9,606.00
Labour	3,197.00	7% GST on	9606.00
Standard Menu	0.00		
Specialist Job	50.00	Total Payable	10,278.42
Diagnostics Job	0.00		
Sundry/Others	50.00		
Total(w/o GST)	9,606.00		

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



## Exceptional Journeys

INSURANCE CO.: **INDIA**


Supplementary Parts For Registration No.: **SMX 6597 A**

<b><u>Materials</u></b>		<b><u>Cost (\$)</u></b>
1	Rivet (x10)	50.00 — nec
2	Clips (x10)	30.00 — nec
3	Clips (x10)	20.00 — nec
4	Strut, Fr susp, LH	410.00 — BT
Total Materials		510.00

<b><u>Labour</u></b>		<b><u>Cost (\$)</u></b>
1	Replace LH front undercarriage parts	225.00 —
Total Labour		225.00
Taxable Amount		735.00
7% GST		51.45
<b>Grand total</b>		<b><u>786.45</u></b>

Thank You.

Yours faithfully  
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

  
LOI AI TING  
SENIOR OFFICER - ADMIN  
TEL: 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240